



Reserve Studies by

Reserve Funding



Arbor Ridge P.U.D. Homeowners Association-Master

NW Laidlaw Road & NW 174th Avenue
Beaverton, Oregon 97006
July 15, 2014

Prepared by:
D.L. "Dan" Huntley, RS, PRA
Tamarra "Tammy" Axton, PRA
Ray Axton, PRA



Reserve Study Professionals credentialed by
Community Association Institute (RS)and
Association of Professional Reserve Analysts (PRA)

ARBOR RIDGE P.U.D. HOMEOWNERS ASSOCIATION-MASTER

Executive Summary

Fiscal Year of Report

January 1, 2016 to December 31, 2016

Number of Lots 570

Parameters

Beginning Balance \$276,654

Fiscal Year 2016 Suggested Contribution \$34,200

Average Annual Reserve Assessment Per Lot \$60.00

Prior Year's Actual Contribution \$30,504

Fiscal Year Projected Interest Rate .05%

Fiscal Year Inflation Rate 2.38%

Annual Increase To Suggested Contribution 4.87%

Lowest Cash Balance Over 30 Years (Threshold) \$101,716

This work is copyright and has been supplied under contract to the Association and/or its representatives. Apart from the Client's right to reproduce and distribute copies of this report as required by its governing documents or state law, no part of this reserve study may be reproduced by any process without prior written permission from Reserve Studies by Reserve Funding or its parent company Reserve Funding (Western States Subdivision Consulting). Requests and inquiries concerning reproduction and rights should be addressed to Reserve Studies by Reserve Funding at its main office at 16869 SW 65th Avenue, Suite 366, Lake Oswego, OR 97035.

**16869 SW 65th Avenue, Suite 366
Lake Oswego, Oregon 97035
800-301-3411**

TABLE OF CONTENTS
Arbor Ridge P.U.D. Homeowners Association-Master

Executive Summary	2
Category Detail Index	4
Base Line Assessment Funding Model Summary	6
Base Assessment Funding Model Projection	13
Funding Goals & Plans	14
Base Line Funding Model & Fully Funded Comparison Chart	15
Asset Current Cost by Category	16
Component Summary	17
Annual Expenditure Detail	19
Annual Expenditure Detail	25
Detail Report by Category	31
Revenue Ruling 70-604	69
Maintenance Plan	70
Member Summary Report	71

PART I • EXECUTIVE SUMMARY

Executive Report - OR	1-1
-----------------------------	-----

PART II • RESERVE STUDY

Part III • Information About Your Reserve Study

Important Information	3-1
Introduction	3-2
Funding Options	3-2
Types of Reserve Studies	3-3
The Reserve Study: A Physical and a Financial Analysis	3-3
Definitions	3-9
Your Reserve Study is a Multi-Purpose Tool	3-10

**Arbor Ridge P.U.D. Homeowners Association-Master
Category Detail Index**

Asset ID	Description	Replacement	Page
Moon Valley Terrace			
1012	Asphalt: Overlay-Moon Valley Terrace	2031	31
1027	Asphalt: Repairs-Moon Valley Terrace	2019	35
1013	Asphalt: Sealcoat-Moon Valley Terrace	2018	39
1022	Concrete: Flatwork-Sidewalks-Moon Valley	2016	47
1019	Curb-Gutter: Moon Valley	2016	49
1039	StormDrains: Moon Valley Terrace	2031	63
Silver Creek Place			
1014	Asphalt: Overlay-Silver Creek Place	2031	33
1032	Asphalt: Repairs-Silver Creek Place	2019	37
1015	Asphalt: Sealcoat-Silver Creek Place	2018	41
1023	Concrete: Flatwork-Sidewalks-Silver Creek	2016	48
1020	Curb-Gutter: Silver Creek Place	2016	50
1040	Lighting: Fixtures-Silver Creek Place-Street Light	2021	57
1041	Lighting: Power-Silver Creek Place-Street Light(2031	58
1037	StormDrains: Silver Creek Place	2031	64
Tatum Ranch Place			
1016	Asphalt: Overlay-Tatum Ranch Place	2031	34
1033	Asphalt: Repairs-Tatum Ranch Place	2019	38
1017	Asphalt: Sealcoat-Tatum Ranch Place	2018	42
1018	Curb-Gutter: Tatum Ranch	2016	51
1038	Storm Drains: Tatum Ranch Place	2031	62
All Lots			
1001	Asphalt: Overlay-Path	2031	32
1031	Asphalt: Repairs-Path	2016	36
1002	Asphalt: Sealcoat-Path	2018	40
1006	Bark Dust: Replace	2017	43
1007	Brick: Pilaster-Wall	2016	44
1004	Bridge: Wooden-Replacement	2026	45
1024	Concrete: Flatwork-Sidewalks-Common Area	2016	46
1011	Fence: Chain Link	2031	52
1010	Fence: Vinyl	2026	53
1025	Fence: Vinyl-Wash	2020	54
1005	Landscaping: Plants & Arborvitae	2016	55
1009	Lighting: Fixtures-Monuments	2016	56

**Arbor Ridge P.U.D. Homeowners Association-Master
Category Detail Index**

Asset ID	Description	Replacement	Page
<i>All Lots Continued...</i>			
1021	Mailboxes: Replace	2031	59
1035	Signs: Common Area	2016	60
1008	Signs: Monument	2016	61
1026	Trees: Renovation-Removal-Trimming	2016	65
1003	Walls: Retaining	2016	66
1036	Walls: Retaining-Inspection	2025	68
	Total Funded Assets	37	
	Total Unfunded Assets	<u>0</u>	
	Total Assets	37	

**Arbor Ridge P.U.D. Homeowners Association-Master
Base Line Assessment Funding Model Summary**

Report Date	July 15, 2014
Account Number	TMG
Version	1 (2016) Level III
Budget Year Beginning	January 01, 2016
Budget Year Ending	December 31, 2016
Total Units	570

<i>Report Parameters</i>	
Inflation	2.38%
Interest Rate on Reserve Deposit	0.05%
2016 Beginning Balance	\$276,653.58

**Current Assessment Funding Model Summary
Cash Flow Time Value of Money Threshold Funding**

BUSINESS JUDGEMENT RULE

To avoid personal liability for their actions/decisions, directors must perform their fiduciary duties "with such care, including reasonable inquiry, as an ordinarily prudent person in a like position would use under similar circumstances."

NOTE: The Board MUST (under the new statutes) - Changes to ORS 94.595 & 100.175 by Senate Bill 963B in 2009

- (3)(a) The board of directors of the association annually shall conduct a reserve study or review and update of an existing study to determine reserve account requirements. Subject to subsection (8) of this section, after review of the reserve study or reserve study update, the board of directors may, without any action of owners:
 - (A) Adjust the amount of payments as indicated by the study or update; and
 - (B) Provide for other reserve items that the board of directors, in its discretion, may deem appropriate.

**Arbor Ridge P.U.D. Homeowners Association-Master
Base Line Assessment Funding Model Summary**

(b) The reserve study shall:

(A) Identify all items for which reserves are or will be established;

**(B) Include the estimated remaining useful life of each item as of the date of the reserve study;
and**

**(C) Include for each item, as applicable, an estimated cost of maintenance and repair and
replacement at the end of the item's useful life.**

**(8)(a) Except as provided under paragraph (b) of this section, unless the board of directors
under subsection (3) of this section determines that the reserve account will be adequately
funded for the following year, the board of directors or the owners may not vote to eliminate
funding a reserve account required under this section or under the declaration or bylaws.**

**(b) Following the turnover meeting described in ORS 94.609 & ORS 100.210 on an annual
basis, the board of directors, with the approval of all owners, may elect not to fund the reserve
account for the following year. (Daniel Zimberoff Attorney-Barker Martin)**

- **This reserve study is for budget and planning purposes and identifies the status of the reserve
fund and schedules the anticipated major commonly owned item replacements.**

**This reserve study will also estimate the expected useful life and remaining useful life of the
building and site components or systems, and will provide an estimate replacement or
refurbishment cost for those components or systems. Major components or systems may
include, but are not limited to, painting, gutters and downspouts, mailboxes, roofing, siding,
windows, doors, paving, mechanical equipment, common area furnishings and amenities and
other commonly owned systems or items.**

- **The scope of work identified within our contract is to provide the association with an
"Updated No-Site Visit" (level III) reserve study which includes:**

Component/System Inventory

Expected Useful Life and Remaining Useful Life Estimates

Condition Assessment (based upon on-site visual observations if applicable).

Component/System Replacement Schedule and Estimated Pricing

**Arbor Ridge P.U.D. Homeowners Association-Master
Base Line Assessment Funding Model Summary**

**Identify Current Reserve Account Balance
30 Year Funding Plan**

- **How to Use a Reserve Study**

The documents included within the reserve study are intended to be used as guidelines and estimates. It is nearly impossible to know exactly when a building component system will fail; however, an estimation of useful life based on similar product history and professional experience is used to estimate the time of replacement and associated costs. All costs included within this reserve study should be used as budgeting figures. For exact pricing, a qualified, licensed contractor should be contacted to provide a bid for any anticipated replacements.

The replacement schedule lists all known components and systems that are anticipated to "wear out" or fail within 30 years. Items which are anticipated to be replaced or repaired in the current year are not included within the reserve study as those items should already be budgeted for, and scheduled to be replaced or repaired.

On the reserve schedule, review which items are anticipated to fail in the near future, and keep a close eye on them. It is always better to replace items prior to failure to eliminate the opportunity for surrounding components or associated systems to be affected. Be cognizant of items scheduled for replacement or repair within 2-3 years of the current year. Remember, items listed are scheduled based on history and replacement or repair is scheduled as an estimate. Items commonly fail sooner or later than the estimated date.

- **Disclosures**

- **General - The Arbor Ridge P.U.D. Homeowners Association-Master and Reserve Studies by Reserve Funding have no professional or personal involvements with each other, other than the scope of work identified in the reserve study contract. This relationship cannot be perceived as a conflict of interest.**
- **Physical Analysis - If an on-site reserve study was performed observations were limited to visual observations only. Destructive testing (invasive testing) was not performed. Any items that were not clearly visible at the time of the site observation were not viewed, and therefore were not included in the drafting of this reserve study.**

**Arbor Ridge P.U.D. Homeowners Association-Master
Base Line Assessment Funding Model Summary**

- **Measurements - Measuring and inventory (+/- 10%) were identified via a combination of on-site physical measurements, previous reserve study and/or drawing take-offs. Drawing sets (if used) were provided by the property manager or Declarant for our use relating only to the reserve study scope of work.**
- **Reliance on Client Data - Data received from property management, association representatives and/or Declarant is deemed reliable by Reserve Funding. Such data may include financial information, physical deficiencies or physical conditions, quantity of physical assets, or historical issues.**
- **Scope - The Reserve Study is a reflection of information provided to the Consultant and assembled for the Association's use, not for the purpose of performing an audit, quality/forensic analysis, or background checks of historical records.**
- **Reserve Balance - The actual or projected (estimated) total presented in this reserve study is based upon information provided or collected and was not audited.**
- **Reserve Projects -Information provided or collected for the purpose of this reserve study will be considered reliable and should not be considered a project audit or quality inspection.**
- **Adjustments to Reserve Study - Should components suggested by Consultant be removed from the reserve study or any life cycles or costs other than current bids, engineering construction standards, or current component history be used in this reserve study the Client accepts full responsibility for the results of the reserve study and is not warranted by Consultant.**
- **Information Provided - Quantity, design and material information included in this report was provided in part by the Association and is subject to course of construction changes.**
- **Limitations on Inventory -The following items, but not limited to, are not included in the physical analysis because they have a useful life greater than 30 years. Grading/drainage, foundations/footings, party walls, bearing and shear walls, perimeter walls, beams, columns and girders, sub floors, unfinished floors, concrete stair surfaces, windows, exterior doors, window and door frames, plumbing system, flues (chimneys), air delivery or return systems, ducts, chutes, conduits, pipes, plumbing, sanitary sewage and storm drains, wire, telephone, cable, central television system, sprinklers systems and internet lines.**

**Arbor Ridge P.U.D. Homeowners Association-Master
Base Line Assessment Funding Model Summary**

- **Warranty or Guaranty - This reserve study and its recommendations should not be construed in any way to constitute a warranty or guaranty regarding the current or future performance of the components. Components will be replaced as required, not necessarily in their expected replacement year.**
- **Annual Updates - Often times there can be a significant expenditure in those years that exceeds the life of the reserve study. Hence, annual updates should be done to allow adjustments in the reserve contribution each year if required.**
- **Tax Consequences - The tax consequences are not considered in this reserve study due to the uncertainty of all factors affecting net taxable income and the election of the tax form to be filed.**
- **If applicable we recommend a building envelope (water intrusion) inspection every six years and a roofing inspection every six years (not funded in the reserve).**
- **House Bill 955 (HB 955), in Oregon since 1/1/2006, specifically calls for the provision of a reserve study, reserve study update, maintenance plan and reserve summary. ORS 94.595 states that: "The board of directors of the association annually shall conduct a reserve study, or review and update an existing reserve study to determine the reserve study requirements". In addition ORS 94.595 (3)(B)(c) and ORS 100.175 (3)(C)(c) further require that a Reserve Study Update be done each year.**
- **House Bill 2665 (Chapter 409, Oregon Laws 2007) revises portions on SB 955 by removing the requirement for a maintenance plan from the reserve study and makes it a separate requirement. Also, after 9/27/2007 HB 2665 no longer requires that owners be provided a reserve summary of the reserve study or any revisions thereto.**
- **Further House Bill 2665 makes windows and unit access doors, except for glazing and screening, general common elements, unless Declaration provides otherwise, (Sec 5).**
- **NOTE: Management or the Board shall notify the reserve study provider if the windows and doors are the responsibility of the Association and if so, will be added to the next update of the reserve study. Management or the Association to provide the count of windows and doors including type and size.**

**Arbor Ridge P.U.D. Homeowners Association-Master
Base Line Assessment Funding Model Summary**

- **Preparation of a Reserve Study**

Data is collected from many sources to prepare a reserve study and a variety of document reviews, interviews, and site observations are required to adequately fulfill our duties as a reserve provider. The following sources, but not limited to, and methods were utilized in the preparation of this reserve study document:

Property Management Personnel Interviews

As built Plans and Specifications Document Reviews

On-site Observations - If Applicable

In-house company consultations with accredited RS and PRA personnel

Discussions with Engineering or Architectural Consultants

RS Means Facilities Maintenance & Repair Cost Data, 22nd Edition (2015) printed manual

Interviewing General Contractor Consultants

- A tabular list of commonly owned items has been developed and given a current condition grade, expected useful life, and remaining useful life. A portion of that data will determine in what year it is estimated the component should be replaced.
- **Property Information**
- **Original Starting Date of Reserve Study - Unless otherwise indicated, we have used January 1, 2001 to begin aging the original components in this reserve study.**
- **Number of Units/Lots and Location - This reserve study is a total of 570 Lots located in Beaverton, Oregon.**
- **Date of Last Reserve Study (if applicable) - The last plan take-off physical analysis done by Reserve Funding by WSSC was completed on October 15, 2004.**
- **NOTE: All interest accrued from reserve savings account(s) must remain in the reserve savings account(s) and not used as an off-set for operating expenses.**

**Arbor Ridge P.U.D. Homeowners Association-Master
Base Line Assessment Funding Model Summary**

- **Funding Required - A minimum balance of \$101,716.00 has been used over the thirty years of this reserve study with an average annual reserve assessment of \$60.00 per Lot and an annual increase of 4.87% to reach 70% full funding within the thirty years of the reserve study.**
- **NOTE: The board/management has expressed a concern regarding the retaining walls and the paths. We suggest the board seek out a qualified, bonded and licensed contractor(s) to review these concerns and provide the Reserve Study provider with and copy of the results so that they can become a part of the reserve study by reference .**

The industry standards for percent funded are:

0% to 29% - Poor

30% to 69% - Fair

70% to 100% - Good

This association is 77% funded on 1/1/2016.

Base Line Funding Model Summary of Calculations

Required Annual Contribution	\$34,200.00
<i>\$60.00 per unit annually</i>	
Average Net Annual Interest Earned	\$124.68
Total Annual Allocation to Reserves	\$34,324.68
<i>\$60.22 per unit annually</i>	

**Arbor Ridge P.U.D. Homeowners Association-Master
Base Assessment Funding Model Projection**

Beginning Balance: \$276,654

Year	Current Cost	Annual Contribution	Annual Interest	Annual Expenditures	Projected Ending Reserves	Fully Funded Reserves	Percent Funded
2016	616,388	34,200	125	61,495	249,483	325,820	77%
2017	631,058	35,866	140	4,403	281,086	359,056	78%
2018	646,077	37,612	158	2,448	316,408	395,750	80%
2019	661,454	39,444	175	6,279	349,748	430,214	81%
2020	677,196	41,365	193	5,801	385,504	466,722	83%
2021	693,314	43,379	211	5,997	423,098	504,666	84%
2022	709,815	45,492	234		468,824	550,292	85%
2023	726,708	47,707	254	7,825	508,961	589,978	86%
2024	744,004	50,031	278	3,211	556,059	636,043	87%
2025	761,711	52,467	301	6,630	602,197	680,623	88%
2026	779,840	55,022	167	322,996	334,391	410,757	81%
2027	798,400	57,702	193	5,571	386,715	452,771	85%
2028	817,402	57,702	216	11,733	432,900	490,523	88%
2029	836,856	57,702	241	7,944	482,899	533,885	90%
2030	856,773	57,702	270		540,871	587,165	92%
2031	877,164	57,702	51	496,908	101,716	145,771	70%
2032	898,041	55,798	74	9,310	148,278	182,459	81%
2033	919,414	53,956	96	9,900	192,431	220,442	87%
2034	941,296	52,176	121	2,367	242,361	267,899	90%
2035	963,699	50,454	142	8,388	284,569	311,524	91%
2036	986,635	48,789	130	74,228	259,260	291,435	89%
2037	1,010,117	47,179	150	7,048	299,540	339,158	88%
2038	1,034,158	45,622	166	12,778	332,551	383,427	87%
2039	1,058,771	44,117	183	10,050	366,800	432,642	85%
2040	1,083,970	42,661	198	13,404	396,255	480,868	82%
2041	1,109,768	41,253	214	9,599	428,123	535,269	80%
2042	1,136,181	39,892	234		468,248	601,814	78%
2043	1,163,222	38,575	247	12,525	494,546	658,699	75%
2044	1,190,906	37,302	259	13,196	518,911	717,577	72%
2045	1,219,250	36,071	272	10,612	544,642	781,783	70%

FUNDING GOALS AND FUNDING PLANS

EXPLANATION OF FUNDING GOALS

In a **Full Reserve Study**, the reserve provider conducts a component inventory, a condition assessment (based upon on-site visual observations), and life and valuation estimates to determine both a “fund status” and “funding plan”.

In an **Update with site inspection**, the reserve provider conducts a component inventory (verification only, not quantification unless new components have been added to the inventory), a condition assessment (based upon on-site visual observations), and life and valuation estimates to determine both the “fund status and “funding plan.”

In an **Update without site inspection**, the reserve provider conducts life and valuation estimates to determine the “fund status” and “funding plan.”

EXPLANATION OF FUNDING PLANS

Baseline Funding Model. The goal of this funding method is to keep the reserve cash balance above zero. This means that while each individual component may not be fully funded, the reserve balance overall does not drop below zero during the projected period. An association using this funding method must understand that even a minor reduction in a component’s remaining useful life can result in a deficit in the reserve cash balance.

Greatest risk to Client for a special assessment


Threshold Funding Model. This method is based upon the cash flow funding concept. The minimum reserve cash balance in threshold funding, however, is set at a predetermined dollar or percent amount (other than zero) and Client may select a dollar amount or a percent amount. **Lesser risk to Client for a special assessment**

Full Funding Model (Proportional Funding)---Given that the basis of funding for reserves is to distribute the costs of the replacements over the lives of the components in question, it follows that the ideal level of reserves will be proportionately related to those lives and costs. If an association has a component with an expected estimated useful life of ten years, it will set aside approximately one-tenth of the replacement cost each year. At the end of three years, one will expect three-tenths of the replacement cost to have accumulated, and if so, that component will be “fully-funded.” This model is important in that it is a measure of the adequacy of an association’s reserves at any one point of time, and is independent of any particular method which may have been used for past funding or may be under consideration for future funding. This formula represents a snapshot in time and is based upon current replacement cost, independent of future inflationary or investment factors:

Fully Funded Reserves = **Age divided by Useful Life the results multiplied by Current Replacement Cost**


When an association’s total accumulated reserves for all components meet this criterion, its reserves are considered “fully-funded.” **Least risk to Client for a special assessment.**

**Arbor Ridge P.U.D. Homeowners Association-Master
Base Line Funding Model & Fully Funded Comparison Chart**



The Current Assessment Funding Model is based on the current annual assessment, parameters, and reserve fund balance. Because it is calculated using the current annual assessment, it will give the accurate projection of how well the association is funded for the next 30 years of planned reserve expenditures.

Asset Current Cost by Category



Arbor Ridge P.U.D. Homeowners Association-Master

Beaverton, Oregon 97006

Component Summary

Description	Future Cost	Useful Life	Remaining Life	Adjustment	Distribution	Required Contribution	Ideally Funded
Moon Valley Terrace							
Asphalt: Overlay-Moon Valley Terrace	8,112	30	15		2,850	232.21	2,850
Asphalt: Repairs-Moon Valley Terrace	575	5	3		214	80.13	214
Asphalt: Sealcoat-Moon Valley Terra..	697	5	2		399	99.24	399
Concrete: Flatwork-Sidewalks-Moon ..	2,525	10	0	5	2,525	212.60	2,525
Curb-Gutter: Moon Valley	2,104	12	0	3	2,104	154.67	2,104
StormDrains: Moon Valley Terrace	<u>3,558</u>	30	15		<u>0</u>	<u>157.66</u>	<u>1,250</u>
Moon Valley Terrace - Total	\$17,570				\$8,092	\$937	\$9,342
Silver Creek Place							
Asphalt: Overlay-Silver Creek Place	8,752	30	15		3,075	250.55	3,075
Asphalt: Repairs-Silver Creek Place	889	5	3		331	123.86	331
Asphalt: Sealcoat-Silver Creek Place	791	5	2		453	112.62	453
Concrete: Flatwork-Sidewalks-Silver ..	3,120	10	0	5	3,120	262.72	3,120
Curb-Gutter: Silver Creek Place	2,600	12	0	3	2,600	191.14	2,600
Lighting: Fixtures-Silver Creek Place-..	208	20	5		139	9.19	139
Lighting: Power-Silver Creek Place-S..	263	30	15		0	11.67	92
StormDrains: Silver Creek Place	<u>3,558</u>	30	15		<u>0</u>	<u>157.66</u>	<u>1,250</u>
Silver Creek Place - Total	\$20,181				\$9,718	\$1,119	\$11,060
Tatum Ranch Place							
Asphalt: Overlay-Tatum Ranch Place	2,375	30	15		835	68.00	835
Asphalt: Repairs-Tatum Ranch Place	199	5	3		74	27.68	74
Asphalt: Sealcoat-Tatum Ranch Place	204	5	2		117	29.06	117
Curb-Gutter: Tatum Ranch	1,808	12	0	3	1,808	132.91	1,808
Storm Drains: Tatum Ranch Place	<u>3,558</u>	30	15		<u>0</u>	<u>157.66</u>	<u>1,250</u>
Tatum Ranch Place - Total	\$8,144				\$2,834	\$415	\$4,084
All Lots							
Asphalt: Overlay-Path	7,702	30	15		2,706	220.48	2,706
Asphalt: Repairs-Path	846	5	0		846	126.77	846
Asphalt: Sealcoat-Path	756	5	2		433	107.69	433
Bark Dust: Replace	4,403	2	1		2,150	1,502.08	2,150
Brick: Pilaster-Wall	7,500	15	0		7,500	472.98	7,500
Bridge: Wooden-Replacement	22,141	25	10		10,500	771.25	10,500
Concrete: Flatwork-Sidewalks-Comm..	5,582	10	0	5	5,582	470.07	5,582
Fence: Chain Link	361,012	30	15		77,330	12,545.68	126,842
Fence: Vinyl	235,505	25	10		111,686	8,203.64	111,686
Fence: Vinyl-Wash	5,801	6	4		1,760	672.79	1,760
Landscaping: Plants & Arborvitae	6,000	10	0	5	6,000	505.23	6,000
Lighting: Fixtures-Monuments	1,110	8	0	7	1,110	111.52	1,110
Mailboxes: Replace	80,022	30	15		0	3,546.21	28,116
Signs: Common Area	1,000	10	0	5	1,000	84.21	1,000
Signs: Monument	4,800	10	0	5	4,800	404.19	4,800

Arbor Ridge P.U.D. Homeowners Association-Master
 Beaverton, Oregon 97006
Component Summary

Description	Future Cost	Useful Life	Remaining Life	Adjustment	Distribution	Required Contribution	Ideally Funded
<i>All Lots continued...</i>							
Trees: Renovation-Removal-Trimming	12,500	10	0	5	12,500	1,052.57	12,500
Walls: Retaining	10,000	10	0	5	10,000	842.05	10,000
Walls: Retaining-Inspection	<u>1,315</u>	10	9		<u>106</u>	<u>89.35</u>	<u>106</u>
All Lots - Total	\$767,995				\$256,010	\$31,729	\$333,639
Grand Total:	<u>\$813,890</u>				<u>\$276,654</u>	<u>\$34,200</u>	<u>\$358,125</u>

**Arbor Ridge P.U.D. Homeowners Association-Master
Annual Expenditure Detail**

Description	Expenditures
Replacement Year 2016	
Asphalt: Repairs-Path	846
Brick: Pilaster-Wall	7,500
Concrete: Flatwork-Sidewalks-Common Area	5,582
Concrete: Flatwork-Sidewalks-Moon Valley	2,525
Concrete: Flatwork-Sidewalks-Silver Creek	3,120
Curb-Gutter: Moon Valley	2,104
Curb-Gutter: Silver Creek Place	2,600
Curb-Gutter: Tatum Ranch	1,808
Landscaping: Plants & Arborvitae	6,000
Lighting: Fixtures-Monuments	1,110
Signs: Common Area	1,000
Signs: Monument	4,800
Trees: Renovation-Removal-Trimming	12,500
Walls: Retaining	10,000
Total for 2016	\$61,495
Replacement Year 2017	
Bark Dust: Replace	4,403
Total for 2017	\$4,403
Replacement Year 2018	
Asphalt: Sealcoat-Moon Valley Terrace	697
Asphalt: Sealcoat-Path	756
Asphalt: Sealcoat-Silver Creek Place	791
Asphalt: Sealcoat-Tatum Ranch Place	204
Total for 2018	\$2,448
Replacement Year 2019	
Asphalt: Repairs-Moon Valley Terrace	575
Asphalt: Repairs-Silver Creek Place	889
Asphalt: Repairs-Tatum Ranch Place	199
Bark Dust: Replace	4,615
Total for 2019	\$6,279
Replacement Year 2020	
Fence: Vinyl-Wash	5,801
Total for 2020	\$5,801

**Arbor Ridge P.U.D. Homeowners Association-Master
Annual Expenditure Detail**

Description	Expenditures
Replacement Year 2021	
Asphalt: Repairs-Path	951
Bark Dust: Replace	4,838
Lighting: Fixtures-Silver Creek Place-Street Light	208
Total for 2021	<u>\$5,997</u>
 <i>No Replacement in 2022</i>	
Replacement Year 2023	
Asphalt: Sealcoat-Moon Valley Terrace	784
Asphalt: Sealcoat-Path	851
Asphalt: Sealcoat-Silver Creek Place	890
Asphalt: Sealcoat-Tatum Ranch Place	230
Bark Dust: Replace	5,071
Total for 2023	<u>\$7,825</u>
Replacement Year 2024	
Asphalt: Repairs-Moon Valley Terrace	647
Asphalt: Repairs-Silver Creek Place	1,000
Asphalt: Repairs-Tatum Ranch Place	224
Lighting: Fixtures-Monuments	1,340
Total for 2024	<u>\$3,211</u>
Replacement Year 2025	
Bark Dust: Replace	5,315
Walls: Retaining-Inspection	1,315
Total for 2025	<u>\$6,630</u>
Replacement Year 2026	
Asphalt: Repairs-Path	1,070
Bridge: Wooden-Replacement	22,141
Concrete: Flatwork-Sidewalks-Common Area	7,063
Concrete: Flatwork-Sidewalks-Moon Valley	3,194
Concrete: Flatwork-Sidewalks-Silver Creek	3,947
Fence: Vinyl	235,505
Fence: Vinyl-Wash	6,680
Landscaping: Plants & Arborvitae	7,591
Signs: Common Area	1,265

**Arbor Ridge P.U.D. Homeowners Association-Master
Annual Expenditure Detail**

Description	Expenditures
<i>Replacement Year 2026 continued...</i>	
Signs: Monument	6,073
Trees: Renovation-Removal-Trimming	15,815
Walls: Retaining	12,652
Total for 2026	<u>\$322,996</u>
Replacement Year 2027	
Bark Dust: Replace	5,571
Total for 2027	<u>\$5,571</u>
Replacement Year 2028	
Asphalt: Sealcoat-Moon Valley Terrace	882
Asphalt: Sealcoat-Path	957
Asphalt: Sealcoat-Silver Creek Place	1,001
Asphalt: Sealcoat-Tatum Ranch Place	258
Curb-Gutter: Moon Valley	2,790
Curb-Gutter: Silver Creek Place	3,448
Curb-Gutter: Tatum Ranch	2,398
Total for 2028	<u>\$11,733</u>
Replacement Year 2029	
Asphalt: Repairs-Moon Valley Terrace	728
Asphalt: Repairs-Silver Creek Place	1,125
Asphalt: Repairs-Tatum Ranch Place	251
Bark Dust: Replace	5,839
Total for 2029	<u>\$7,944</u>
<i>No Replacement in 2030</i>	
Replacement Year 2031	
Asphalt: Overlay-Moon Valley Terrace	8,112
Asphalt: Overlay-Path	7,702
Asphalt: Overlay-Silver Creek Place	8,752
Asphalt: Overlay-Tatum Ranch Place	2,375
Asphalt: Repairs-Path	1,203
Bark Dust: Replace	6,121
Brick: Pilaster-Wall	10,673
Fence: Chain Link	361,012

**Arbor Ridge P.U.D. Homeowners Association-Master
Annual Expenditure Detail**

Description	Expenditures
<i>Replacement Year 2031 continued...</i>	
Lighting: Power-Silver Creek Place-Street Light(263
Mailboxes: Replace	80,022
Storm Drains: Tatum Ranch Place	3,558
StormDrains: Moon Valley Terrace	3,558
StormDrains: Silver Creek Place	3,558
Total for 2031	<u>\$496,908</u>
Replacement Year 2032	
Fence: Vinyl-Wash	7,693
Lighting: Fixtures-Monuments	1,617
Total for 2032	<u>\$9,310</u>
Replacement Year 2033	
Asphalt: Sealcoat-Moon Valley Terrace	992
Asphalt: Sealcoat-Path	1,076
Asphalt: Sealcoat-Silver Creek Place	1,126
Asphalt: Sealcoat-Tatum Ranch Place	290
Bark Dust: Replace	6,415
Total for 2033	<u>\$9,900</u>
Replacement Year 2034	
Asphalt: Repairs-Moon Valley Terrace	819
Asphalt: Repairs-Silver Creek Place	1,266
Asphalt: Repairs-Tatum Ranch Place	283
Total for 2034	<u>\$2,367</u>
Replacement Year 2035	
Bark Dust: Replace	6,724
Walls: Retaining-Inspection	1,664
Total for 2035	<u>\$8,388</u>
Replacement Year 2036	
Asphalt: Repairs-Path	1,354
Concrete: Flatwork-Sidewalks-Common Area	8,936
Concrete: Flatwork-Sidewalks-Moon Valley	4,041
Concrete: Flatwork-Sidewalks-Silver Creek	4,994
Landscaping: Plants & Arborvitae	9,604

**Arbor Ridge P.U.D. Homeowners Association-Master
Annual Expenditure Detail**

Description	Expenditures
<i>Replacement Year 2036 continued...</i>	
Signs: Common Area	1,601
Signs: Monument	7,683
Trees: Renovation-Removal-Trimming	20,008
Walls: Retaining	16,007
Total for 2036	\$74,228
Replacement Year 2037	
Bark Dust: Replace	7,048
Total for 2037	\$7,048
Replacement Year 2038	
Asphalt: Sealcoat-Moon Valley Terrace	1,116
Asphalt: Sealcoat-Path	1,211
Asphalt: Sealcoat-Silver Creek Place	1,266
Asphalt: Sealcoat-Tatum Ranch Place	327
Fence: Vinyl-Wash	8,859
Total for 2038	\$12,778
Replacement Year 2039	
Asphalt: Repairs-Moon Valley Terrace	921
Asphalt: Repairs-Silver Creek Place	1,423
Asphalt: Repairs-Tatum Ranch Place	318
Bark Dust: Replace	7,388
Total for 2039	\$10,050
Replacement Year 2040	
Curb-Gutter: Moon Valley	3,700
Curb-Gutter: Silver Creek Place	4,572
Curb-Gutter: Tatum Ranch	3,180
Lighting: Fixtures-Monuments	1,952
Total for 2040	\$13,404
Replacement Year 2041	
Asphalt: Repairs-Path	1,522
Bark Dust: Replace	7,744
Lighting: Fixtures-Silver Creek Place-Street Light	333
Total for 2041	\$9,599

**Arbor Ridge P.U.D. Homeowners Association-Master
Annual Expenditure Detail**

Description	Expenditures
<i>No Replacement in 2042</i>	
Replacement Year 2043	
Asphalt: Sealcoat-Moon Valley Terrace	1,255
Asphalt: Sealcoat-Path	1,362
Asphalt: Sealcoat-Silver Creek Place	1,424
Asphalt: Sealcoat-Tatum Ranch Place	368
Bark Dust: Replace	8,117
Total for 2043	<u>\$12,525</u>
Replacement Year 2044	
Asphalt: Repairs-Moon Valley Terrace	1,036
Asphalt: Repairs-Silver Creek Place	1,601
Asphalt: Repairs-Tatum Ranch Place	358
Fence: Vinyl-Wash	10,201
Total for 2044	<u>\$13,196</u>
Replacement Year 2045	
Bark Dust: Replace	8,508
Walls: Retaining-Inspection	2,105
Total for 2045	<u>\$10,612</u>

**Arbor Ridge P.U.D. Homeowners Association-Master
Annual Expenditure Detail**

Description	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025
Asphalt: Overlay-Moon Valley Terrace										
Asphalt: Overlay-Path										
Asphalt: Overlay-Silver Creek Place										
Asphalt: Overlay-Tatum Ranch Place										
Asphalt: Repairs-Moon Valley Terrace				575					647	
Asphalt: Repairs-Path	846					951				
Asphalt: Repairs-Silver Creek Place				889					1,000	
Asphalt: Repairs-Tatum Ranch Place				199					224	
Asphalt: Sealcoat-Moon Valley Terrace			697					784		
Asphalt: Sealcoat-Path			756					851		
Asphalt: Sealcoat-Silver Creek Place			791					890		
Asphalt: Sealcoat-Tatum Ranch Place			204					230		
Bark Dust: Replace		4,403		4,615		4,838		5,071		5,315
Brick: Pilaster-Wall	7,500									
Bridge: Wooden-Replacement										
Concrete: Flatwork-Sidewalks-Common Area	5,582									
Concrete: Flatwork-Sidewalks-Moon Valley	2,525									
Concrete: Flatwork-Sidewalks-Silver Creek	3,120									
Curb-Gutter: Moon Valley	2,104									
Curb-Gutter: Silver Creek Place	2,600									
Curb-Gutter: Tatum Ranch	1,808									
Fence: Chain Link										
Fence: Vinyl										
Fence: Vinyl-Wash					5,801					
Landscaping: Plants & Arborvitae	6,000									
Lighting: Fixtures-Monuments	1,110								1,340	
Lighting: Fixtures-Silver Creek Place-Street Li..						208				
Lighting: Power-Silver Creek Place-Street Lig..										
Mailboxes: Replace										
Signs: Common Area	1,000									
Signs: Monument	4,800									
Storm Drains: Tatum Ranch Place										
StormDrains: Moon Valley Terrace										
StormDrains: Silver Creek Place										
Trees: Renovation-Removal-Trimming	12,500									

**Arbor Ridge P.U.D. Homeowners Association-Master
Annual Expenditure Detail**

Description	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025
Walls: Retaining	10,000									
Walls: Retaining-Inspection										1,315
Year Total:	61,495	4,403	2,448	6,279	5,801	5,997		7,825	3,211	6,630

**Arbor Ridge P.U.D. Homeowners Association-Master
Annual Expenditure Detail**

Description	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035
Asphalt: Overlay-Moon Valley Terrace						8,112				
Asphalt: Overlay-Path						7,702				
Asphalt: Overlay-Silver Creek Place						8,752				
Asphalt: Overlay-Tatum Ranch Place						2,375				
Asphalt: Repairs-Moon Valley Terrace				728					819	
Asphalt: Repairs-Path	1,070					1,203				
Asphalt: Repairs-Silver Creek Place				1,125					1,266	
Asphalt: Repairs-Tatum Ranch Place				251					283	
Asphalt: Sealcoat-Moon Valley Terrace			882					992		
Asphalt: Sealcoat-Path			957					1,076		
Asphalt: Sealcoat-Silver Creek Place			1,001					1,126		
Asphalt: Sealcoat-Tatum Ranch Place			258					290		
Bark Dust: Replace		5,571		5,839		6,121		6,415		6,724
Brick: Pilaster-Wall						10,673				
Bridge: Wooden-Replacement	22,141									
Concrete: Flatwork-Sidewalks-Common Area	7,063									
Concrete: Flatwork-Sidewalks-Moon Valley	3,194									
Concrete: Flatwork-Sidewalks-Silver Creek	3,947									
Curb-Gutter: Moon Valley			2,790							
Curb-Gutter: Silver Creek Place			3,448							
Curb-Gutter: Tatum Ranch			2,398							
Fence: Chain Link						361,012				
Fence: Vinyl	235,505									
Fence: Vinyl-Wash	6,680						7,693			
Landscaping: Plants & Arborvitae	7,591									
Lighting: Fixtures-Monuments							1,617			
Lighting: Fixtures-Silver Creek Place-Street Li..										
Lighting: Power-Silver Creek Place-Street Lig..						263				
Mailboxes: Replace						80,022				
Signs: Common Area	1,265									
Signs: Monument	6,073									
Storm Drains: Tatum Ranch Place						3,558				
StormDrains: Moon Valley Terrace						3,558				
StormDrains: Silver Creek Place						3,558				
Trees: Renovation-Removal-Trimming	15,815									

**Arbor Ridge P.U.D. Homeowners Association-Master
Annual Expenditure Detail**

Description	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035
Walls: Retaining	12,652									
Walls: Retaining-Inspection										1,664
Year Total:	322,996	5,571	11,733	7,944		496,908	9,310	9,900	2,367	8,388

**Arbor Ridge P.U.D. Homeowners Association-Master
Annual Expenditure Detail**

Description	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045
Asphalt: Overlay-Moon Valley Terrace										
Asphalt: Overlay-Path										
Asphalt: Overlay-Silver Creek Place										
Asphalt: Overlay-Tatum Ranch Place										
Asphalt: Repairs-Moon Valley Terrace				921					1,036	
Asphalt: Repairs-Path	1,354					1,522				
Asphalt: Repairs-Silver Creek Place				1,423					1,601	
Asphalt: Repairs-Tatum Ranch Place				318					358	
Asphalt: Sealcoat-Moon Valley Terrace			1,116					1,255		
Asphalt: Sealcoat-Path			1,211					1,362		
Asphalt: Sealcoat-Silver Creek Place			1,266					1,424		
Asphalt: Sealcoat-Tatum Ranch Place			327					368		
Bark Dust: Replace		7,048		7,388		7,744		8,117		8,508
Brick: Pilaster-Wall										
Bridge: Wooden-Replacement										
Concrete: Flatwork-Sidewalks-Common Area	8,936									
Concrete: Flatwork-Sidewalks-Moon Valley	4,041									
Concrete: Flatwork-Sidewalks-Silver Creek	4,994									
Curb-Gutter: Moon Valley					3,700					
Curb-Gutter: Silver Creek Place					4,572					
Curb-Gutter: Tatum Ranch					3,180					
Fence: Chain Link										
Fence: Vinyl										
Fence: Vinyl-Wash			8,859						10,201	
Landscaping: Plants & Arborvitae	9,604									
Lighting: Fixtures-Monuments					1,952					
Lighting: Fixtures-Silver Creek Place-Street Li..						333				
Lighting: Power-Silver Creek Place-Street Lig..										
Mailboxes: Replace										
Signs: Common Area	1,601									
Signs: Monument	7,683									
Storm Drains: Tatum Ranch Place										
StormDrains: Moon Valley Terrace										
StormDrains: Silver Creek Place										
Trees: Renovation-Removal-Trimming	20,008									

**Arbor Ridge P.U.D. Homeowners Association-Master
Annual Expenditure Detail**

Description	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045
Walls: Retaining	16,007									
Walls: Retaining-Inspection										2,105
Year Total:	74,228	7,048	12,778	10,050	13,404	9,599		12,525	13,196	10,612

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Asphalt: Overlay-Moon Valley Terrace		4,750 SF	@ \$1.20
Asset ID	1012	Asset Cost	\$5,700.00
Group	Capital	Percent Replacement	100%
Category	Moon Valley Terrace	Future Cost	\$8,111.51
Placed in Service	January 2001		
Useful Life	30		
Replacement Year	2031		
Remaining Life	15		



Remarks:

This component is the overlay of the asphalt street serving 7 lots called Moon Valley Terrace a private street, with addresses 4302, 4316, 4321, 4328, 4333, 4340 and 4345.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Asphalt: Overlay-Path

		4,510 SF	@ \$1.20
Asset ID	1001	Asset Cost	\$5,412.00
Group	Capital	Percent Replacement	100%
Category	All Lots	Future Cost	\$7,701.66
Placed in Service	January 2001		
Useful Life	30		
Replacement Year	2031		
Remaining Life	15		



Remarks:

This component is the overlay of the asphalt pathway for the master association.

Funds may be used to repair the asphalt failure if needed (see Asphalt-S/C-Path.).

The board has expressed a concern (2007) regarding the pathways; hence, we suggest a licensed and bonded contractor review the paths and make a recommendation to the board and management.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Asphalt: Overlay-Silver Creek Place		5,125 SF	@ \$1.20
Asset ID	1014	Asset Cost	\$6,150.00
Group	Capital	Percent Replacement	100%
Category	Silver Creek Place	Future Cost	\$8,751.89
Placed in Service	January 2001		
Useful Life	30		
Replacement Year	2031		
Remaining Life	15		



Remarks:

This component is the overlay of the asphalt street serving 7 lots (Track B) called NW Silver Creek Place, 44, 45, 46, 47, 48, 49, and 50.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Asphalt: Overlay-Tatum Ranch Place		1,391 SF	@ \$1.20
Asset ID	1016	Asset Cost	\$1,669.20
Group	Capital	Percent Replacement	100%
Category	Tatum Ranch Place	Future Cost	\$2,375.39
Placed in Service	January 2001		
Useful Life	30		
Replacement Year	2031		
Remaining Life	15		



Remarks:

This component is the overlay of the asphalt street serving 3 lots called Tatum Ranch Place.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Asphalt: Repairs-Moon Valley Terrace		4,750 SF	@ \$3.75
Asset ID	1027	Asset Cost	\$536.16
Group	Capital	Percent Replacement	3.01%
Category	Moon Valley Terrace	Future Cost	\$575.36
Placed in Service	July 2014		
Useful Life	5		
Replacement Year	2019		
Remaining Life	3		



Remarks:

This component is the repairs required on the 7 lots served by Moon Valley Terrace a private street, with addresses 4302, 4316, 4321, 4328, 4333, 4340 and 4345.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Asphalt: Repairs-Path

		4,510 SF	@ \$3.75
Asset ID	1031	Asset Cost	\$845.62
Group	Capital	Percent Replacement	5%
Category	All Lots	Future Cost	\$845.62
Placed in Service	January 2011		
Useful Life	5		
Replacement Year	2016		
Remaining Life	0		



Remarks:

This component is the repairs required on the pathway.

The asphalt has numerous cracks and subsidence at the present time.

It appears the infrastructure base may be failing under the pathway as there appears to be ground movement.

Funds may be used from the Asphalt-O/L-Path item if needed.

The board has expressed a concern (2007) regarding the pathways; hence, we suggest a licensed and bonded contractor review the paths and make a recommendation to the board and management.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Asphalt: Repairs-Silver Creek Place		5,390 SF	@ \$3.75
Asset ID	1032	Asset Cost	\$828.71
Group	Non-Capital	Percent Replacement	4.1%
Category	Silver Creek Place	Future Cost	\$889.30
Placed in Service	January 2014		
Useful Life	5		
Replacement Year	2019		
Remaining Life	3		



Remarks:

This component is the repairs required on the private street (Track B) called NW Silver Creek Place, serving Lots 44, 45, 46, 47, 48, 49, and 50..

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Asphalt: Repairs-Tatum Ranch Place		1,391 SF	@ \$3.75
Asset ID	1033	Asset Cost	\$185.18
Group	Capital	Percent Replacement	3.55%
Category	Tatum Ranch Place	Future Cost	\$198.72
Placed in Service	July 2014		
Useful Life	5		
Replacement Year	2019		
Remaining Life	3		



Remarks:

This component is the repairs required on the private street.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Asphalt: Sealcoat-Moon Valley Terrace		4,750 SF	@ \$0.14
Asset ID	1013	Asset Cost	\$665.00
Group	Non-Capital	Percent Replacement	100%
Category	Moon Valley Terrace	Future Cost	\$697.03
Placed in Service	September 2013		
Useful Life	5		
Replacement Year	2018		
Remaining Life	2		



Remarks:

This component is the seal coating, and re-striping of the asphalt street serving 7 lots called Moon Valley Terrace with addresses 4302, 4316, 4321, 4328, 4333, 4340 and 4345.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Asphalt: Sealcoat-Path		4,510 SF	@ \$0.16
Asset ID	1002	Asset Cost	\$721.60
Group	Non-Capital	Percent Replacement	100%
Category	All Lots	Future Cost	\$756.36
Placed in Service	September 2013		
Useful Life	5		
Replacement Year	2018		
Remaining Life	2		



Remarks:

This component is the resealing, and re-stripping of the asphalt path for the master association.

The asphalt has numerous cracks and subsidence at the present time.

It appears the infrastructure base may be failing under the pathway as there appears to be ground movement.

Funds may be used from the Asphalt-O/L-Path item if needed.

The board has expressed a concern (2007) regarding the pathways; hence, we suggest a licensed and bonded contractor review the paths and make a recommendation to the board and management.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Asphalt: Sealcoat-Silver Creek Place		5,390 SF	@ \$0.14
Asset ID	1015	Asset Cost	\$754.60
Group	Non-Capital	Percent Replacement	100%
Category	Silver Creek Place	Future Cost	\$790.95
Placed in Service	September 2013		
Useful Life	5		
Replacement Year	2018		
Remaining Life	2		



Remarks:

This component is the sealcoating, and restriping of the asphalt street serving 7 lots (Track B) called NW Silver Creek Place, 44, 45, 46, 47, 48, 49, and 50.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Asphalt: Sealcoat-Tatum Ranch Place

		1,391 SF	@ \$0.14
Asset ID	1017	Asset Cost	\$194.74
Group	Non-Capital	Percent Replacement	100%
Category	Tatum Ranch Place	Future Cost	\$204.12
Placed in Service	September 2013		
Useful Life	5		
Replacement Year	2018		
Remaining Life	2		



Remarks:

This component is the sealcoating, and re-striping of the asphalt street serving 3 lots called Tatum Ranch Place.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Bark Dust: Replace		25,300 SF	@ \$0.17
Asset ID	1006	Asset Cost	\$4,301.00
Group	Non-Capital	Percent Replacement	100%
Category	All Lots	Future Cost	\$4,403.36
Placed in Service	May 2015		
Useful Life	2		
Replacement Year	2017		
Remaining Life	1		



Remarks:

This component is the bark dust spread around the landscaped beds in the common area.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Brick: Pilaster-Wall

		1 Total	@ \$7,500.00
Asset ID	1007	Asset Cost	\$7,500.00
Group	Capital	Percent Replacement	100%
Category	All Lots	Future Cost	\$7,500.00
Placed in Service	January 2001		
Useful Life	15		
Replacement Year	2016		
Remaining Life	0		



Remarks:

This component is an allowance for any work required on the masonry pilasters and walls at the common area fencing and monument, which may have a life expectancy of more than 30 years. However, we have allowed for any repair, maintenace or replacement within the 30 years.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Bridge: Wooden-Replacement

		1 Each	@ \$17,500.00
Asset ID	1004	Asset Cost	\$17,500.00
Group	Capital	Percent Replacement	100%
Category	All Lots	Future Cost	\$22,140.60
Placed in Service	January 2001		
Useful Life	25		
Replacement Year	2026		
Remaining Life	10		



Remarks:

This component is the wooden pedestrian bridge over the wet lands in the common area.

The bridge are mostly glu-lam beams or stringers with Douglas Fir uprightsand wood railings.

Some work was done in 2015 at a cost of\$2,500.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Concrete: Flatwork-Sidewalks-Common Area

		2,326 SF	@ \$12.00
Asset ID	1024	Asset Cost	\$5,582.40
Group	Capital	Percent Replacement	20%
Category	All Lots	Future Cost	\$5,582.40
Placed in Service	January 2001		
Useful Life	10		
Adjustment	5		
Replacement Year	2016		
Remaining Life	0		



Remarks:

This component is 20% of the total concrete sidewalks in the common area excluding private drives, which may need repairs, maintenance or replacement within a 10-year period.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Concrete: Flatwork-Sidewalks-Moon Valley

		1,052 SF	@ \$12.00
Asset ID	1022	Asset Cost	\$2,524.80
Group	Capital	Percent Replacement	20%
Category	Moon Valley Terrace	Future Cost	\$2,524.80
Placed in Service	January 2001		
Useful Life	10		
Adjustment	5		
Replacement Year	2016		
Remaining Life	0		



Remarks:

This component is the repair, maintenance or replacement of 20% of the concrete sidewalk by the private street Moon Valley, which may need work within 10 years.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Concrete: Flatwork-Sidewalks-Silver Creek

		1,300 SF	@ \$12.00
Asset ID	1023	Asset Cost	\$3,120.00
Group	Capital	Percent Replacement	20%
Category	Silver Creek Place	Future Cost	\$3,120.00
Placed in Service	January 2001		
Useful Life	10		
Adjustment	5		
Replacement Year	2016		
Remaining Life	0		



Remarks:

This component is the repair, maintenance or replacement of 20% of the concrete sidewalks on the private street Silver Creek, which may need work within 10 years.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Curb-Gutter: Moon Valley		263 LF	@ \$8.00
Asset ID	1019	Asset Cost	\$2,104.00
Group	Capital	Percent Replacement	100%
Category	Moon Valley Terrace	Future Cost	\$2,104.00
Placed in Service	January 2001		
Useful Life	12		
Adjustment	3		
Replacement Year	2016		
Remaining Life	0		



Remarks:

This component is the repair, maintenance or replacement of the concrete vertical curb and gutter on the private street Moon Valley.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Curb-Gutter: Silver Creek Place		325 LF	@ \$8.00
Asset ID	1020	Asset Cost	\$2,600.00
Group	Capital	Percent Replacement	100%
Category	Silver Creek Place	Future Cost	\$2,600.00
Placed in Service	January 2001		
Useful Life	12		
Adjustment	3		
Replacement Year	2016		
Remaining Life	0		



Remarks:

This component is the repair, maintenance or replacement of the concrete vertical curb and gutter on the private street Silver Creek.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Curb-Gutter: Tatum Ranch

		226 LF	@ \$8.00
Asset ID	1018	Asset Cost	\$1,808.00
Group	Capital	Percent Replacement	100%
Category	Tatum Ranch Place	Future Cost	\$1,808.00
Placed in Service	January 2001		
Useful Life	12		
Adjustment	3		
Replacement Year	2016		
Remaining Life	0		



Remarks:

This component is the repair, maintenance or replacement of the concrete vertical curb and gutters on the private street Tatum Ranch.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Fence: Chain Link

		11,225 LF	@ \$22.60
Asset ID	1011	Asset Cost	\$253,685.00
Group	Capital	Percent Replacement	100%
Category	All Lots	Future Cost	\$361,012.02
Placed in Service	January 2001		
Useful Life	30		
Replacement Year	2031		
Remaining Life	15		



Remarks:

This component is the black, vinyl-coated, chain link fencing around the wet lands and street areas in the common area (NW Laidlaw Road and NW West Union Road).

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Fence: Vinyl

		9,600 LF	@ \$19.39
Asset ID	1010	Asset Cost	\$186,144.00
Group	Capital	Percent Replacement	100%
Category	All Lots	Future Cost	\$235,505.09
Placed in Service	January 2001		
Useful Life	25		
Replacement Year	2026		
Remaining Life	10		



Remarks:

This component is the vinyl, 3-rail fencing around the wet lands in the common area, NW Laidlaw Road , NW West Union Road, and some side streets.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Fence: Vinyl-Wash

		9,600 LF	@ \$0.55
Asset ID	1025	Asset Cost	\$5,280.00
Group	Capital	Percent Replacement	100%
Category	All Lots	Future Cost	\$5,800.89
Placed in Service	May 2014		
Useful Life	6		
Replacement Year	2020		
Remaining Life	4		



Remarks:

This component is the washing of the vinyl, 3-rail fencing around the wet lands in the common area, NW Laidlaw Road , NW West Union Road, and some side streets.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.


These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Landscaping: Plants & Arborvitae

			1 Each	@ \$6,000.00
Asset ID	1005		Asset Cost	\$6,000.00
Group	Non-Capital		Percent Replacement	100%
Category	All Lots		Future Cost	\$6,000.00
Placed in Service	January 2001			
Useful Life	10			
Adjustment	5			
Replacement Year	2016			
Remaining Life	0			



Remarks:

This component is the replacement of any landscape plants, shrubs, trees.

Funds may be used at any time work needs to be done during the 10 years.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Lighting: Fixtures-Monuments

		6 Each	@ \$185.00
Asset ID	1009	Asset Cost	\$1,110.00
Group	Non-Capital	Percent Replacement	100%
Category	All Lots	Future Cost	\$1,110.00
Placed in Service	January 2001		
Useful Life	8		
Adjustment	7		
Replacement Year	2016		
Remaining Life	0		



Remarks:

This component is the area lighting fixtures at the monuments.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Lighting: Fixtures-Silver Creek Place-Street Light

			1 Each	@ \$185.00
Asset ID	1040		Asset Cost	\$185.00
Group	Non-Capital	Percent Replacement		100%
Category	Silver Creek Place	Future Cost		\$208.09
Placed in Service	January 2001			
Useful Life	20			
Replacement Year	2021			
Remaining Life	5			



Remarks:

This component is the area lighting fixtures at the street light on Silver Creek Place.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Lighting: Power-Silver Creek Place-Street Light(

			1 Each	@ \$185.00
Asset ID	1041		Asset Cost	\$185.00
Group	Capital	Percent Replacement		100%
Category	Silver Creek Place	Future Cost		\$263.27
Placed in Service	January 2001			
Useful Life	30			
Replacement Year	2031			
Remaining Life	15			



Remarks:

This component is the area lighting power supply at the street light on Silver Creek Place.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Mailboxes: Replace

		36 Each	@ \$1,562.00
Asset ID	1021	Asset Cost	\$56,232.00
Group	Capital	Percent Replacement	100%
Category	All Lots	Future Cost	\$80,022.18
Placed in Service	January 2001		
Useful Life	30		
Replacement Year	2031		
Remaining Life	15		



Remarks:

This component is the cluster mail boxes located throughout the subdivision.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Signs: Common Area

		2 Each	@ \$500.00
Asset ID	1035	Asset Cost	\$1,000.00
Group	Capital	Percent Replacement	100%
Category	All Lots	Future Cost	\$1,000.00
Placed in Service	January 2001		
Useful Life	10		
Adjustment	5		
Replacement Year	2016		
Remaining Life	0		



Remarks:

This component is the replacement of any signs in the common area excluding monument sign.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Signs: Monument

		2 Each	@ \$2,400.00
Asset ID	1008	Asset Cost	\$4,800.00
Group	Capital	Percent Replacement	100%
Category	All Lots	Future Cost	\$4,800.00
Placed in Service	January 2001		
Useful Life	10		
Adjustment	5		
Replacement Year	2016		
Remaining Life	0		



Remarks:

This component is the entry aluminum lettered monument signs at the corner of Laidlaw and West Union.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Storm Drains: Tatum Ranch Place

Asset ID	1038	1 Total	@ \$2,500.00
Group	Capital	Asset Cost	\$2,500.00
Category	Tatum Ranch Place	Percent Replacement	100%
Placed in Service	January 2001	Future Cost	\$3,557.68
Useful Life	30		
Replacement Year	2031		
Remaining Life	15		



Remarks:

This component is an allowance for the maintenance of the storm drains serving 7 lots (Track B) called NW Tatum Ranch Place, 44, 45, 46, 47, 48, 49, and 50..

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

StormDrains: Moon Valley Terrace

Asset ID	1039	1 Total	@ \$2,500.00
Group	Capital	Asset Cost	\$2,500.00
Category	Moon Valley Terrace	Percent Replacement	100%
Placed in Service	January 2001	Future Cost	\$3,557.68
Useful Life	30		
Replacement Year	2031		
Remaining Life	15		



Remarks:

This component is an allowance for the maintenance of the storm drains serving 7 lots called Moon Valley Terrace with addresses 4302, 4316, 4321, 4328, 4333, 4340 and 4345.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

StormDrains: Silver Creek Place

		1 Total	@ \$2,500.00
Asset ID	1037	Asset Cost	\$2,500.00
Group	Capital	Percent Replacement	100%
Category	Silver Creek Place	Future Cost	\$3,557.68
Placed in Service	January 2001		
Useful Life	30		
Replacement Year	2031		
Remaining Life	15		



Remarks:

This component is an allowance for the maintenance of the storm drains serving 7 lots (Track B) called NW Silver Creek Place, 44, 45, 46, 47, 48, 49, and 50.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Trees: Renovation-Removal-Trimming

		1 Total	@ \$12,500.00
Asset ID	1026	Asset Cost	\$12,500.00
Group	Non-Capital	Percent Replacement	100%
Category	All Lots	Future Cost	\$12,500.00
Placed in Service	January 2001		
Useful Life	10		
Adjustment	5		
Replacement Year	2016		
Remaining Life	0		



Remarks:

This component is an allowance for any tree work in the common area or in the parking strips which consists of 333 trees according to the Tree Inventory Management Plan by Davey Resource Group.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Walls: Retaining

		1 Total	@ \$50,000.00
Asset ID	1003	Asset Cost	\$10,000.00
Group	Capital	Percent Replacement	20%
Category	All Lots	Future Cost	\$10,000.00
Placed in Service	January 2001		
Useful Life	10		
Adjustment	5		
Replacement Year	2016		
Remaining Life	0		



Remarks:

While the Track C retaining walls consists of concrete key-lock blocks, masonry and large ballast rocks that may have a life expectancy of more than 30 years, we have allowed for a portion of the replacement work that may need to be done every 10 years or during the 10 years.

The back yard wall foundation on Oak Street at NW Union Hills Terrace appears to be settling and has separated from the attached wall.

[The board has expressed a concern \(2007\) regarding the retaining walls; We suggest that a licensed and bonded contractor review the walls and make a recommendation to the board and management.](#)

[The Field Summary Report for Track C dated 4/17/2015 by Columbia Geotechnical is an addendum by reference to this Reserve Study.](#)

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Walls: Retaining continued...

the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**Arbor Ridge P.U.D. Homeowners Association-Master
Detail Report by Category**

Walls: Retaining-Inspection

		1 Total	@ \$1,064.00
Asset ID	1036	Asset Cost	\$1,064.00
Group	Capital	Percent Replacement	100%
Category	All Lots	Future Cost	\$1,314.85
Placed in Service	July 2015		
Useful Life	10		
Replacement Year	2025		
Remaining Life	9		



Remarks:

This component is an allowance for the periodic inspection of the retaining wall.

While the retaining wall consists of concrete key-lock blocks and large ballast rocks that may have a life expectancy of more than 30 years, we have allowed for a portion of the replacement work that may need to be done every 10 years or during the 10 years.

The board has expressed a concern (2007) regarding the retaining walls; We suggest that a licensed and bonded contractor review the walls and make a recommendation to the board and management.

The Field Summary Report for Track C dated 4/17/2015 by Columbia Geotechnical is an addendum by reference to this Reserve Study.

The cost and useful life assumptions are based on accepted industry estimates as established by RS Means, Craftsman, Marshall Swift, The National Construction Estimator, National Repair and Remodel Estimator, Dodge Cost Manual, McGraw Hill Professional, assorted independent contractors, various specialists, assorted vendors catalogues, actual quotations or historical costs, Consultant's own experience in like components or as provided by the Client.

The Association should obtain a bid to confirm this estimate.

These costs do not take into consideration any changes to the building code.

Note: This is a provision for an anticipated expense. Should the Association find that the cost of this item is greater or less than the amount provided for herein, this reserve study should be updated to reflect the actual component cost.

**ASSOCIATION RESOLUTION FOR REVENUE RULING 70-604 ELECTION
EXCESS INCOME APPLIED TO THE FOLLOWING YEAR'S ASSESSMENTS**

**RESOLUTION MUST BE VOTED ON BY THE MEMBERSHIP
AT THE ANNUAL MEETING**

ANNUAL RESOLUTION OF THE (Association)_____

**RE: EXCESS INCOME APPLIED TO THE FOLLOWING YEAR'S
ASSESSMENTS REVENUE RULING 70-604**

**WHEREAS, The (Association)_____ is a (State)
_____ corporation duly organized and existing under the laws of the State of
(State) _____;**

and

**WHEREAS, The members desire that the corporation shall act in full accordance with the
rulings and regulations of the Internal Revenue Service;**

and

**NOW, THEREFORE, the members hereby adopt the following resolution by and on behalf
of the (Association) _____:**

**RESOLVED, that any excess of membership income over membership expenses for the year
ending _____20__ shall be applied against the subsequent tax year
member assessment as provided by IRS Revenue Ruling 70-604.**

**This resolution was voted on and made a part of the minutes of the annual meeting of
(Association) _____.**

**BY: _____
President**

**ATTESTED: _____
Secretary**

Form compliant with IRS Ruling 70-604

ARBOR RIDGE P.U.D. HOMEOWNERS ASSOCIATION-MASTER

Maintenance Plan (Will follow later by email)

The current maintenance plan prepared by Reserve Studies by Reserve Funding is attached as an addendum to this reserve study by separate document. The reserve study and the maintenance plan should be filed together as one document.

Each year, during the update process whether Level II or Level III, the maintenance plan should be updated and revised as required.

The maintenance plan should be used as a guide for the timing of maintenance procedures and the forms attached to the maintenance plan used in order to have an on-going record of maintenance done.

This maintenance plan may be the original maintenance plan done (Level 1) or an update of a previous maintenance plan.

If component materials have been changed or substituted the Client should notify Reserve Funding by Reserve Studies so that changes can be taken into consideration during the preparation of the reserve study.

**Arbor Ridge P.U.D. Homeowners Association-Master
Member Summary Report**

Description	Date In Service	Replacement Year	Current Cost	Useful Life	Adjustment	Remaining	Future Cost	Quantity	Unit Cost
Asphalt: Overlay-Moon Valley Terra..	2001	2031	5,700	30	0	15	8,112	4750 @	1.20
Asphalt: Overlay-Path	2001	2031	5,412	30	0	15	7,702	4510 @	1.20
Asphalt: Overlay-Silver Creek Place	2001	2031	6,150	30	0	15	8,752	5125 @	1.20
Asphalt: Overlay-Tatum Ranch Place	2001	2031	1,669	30	0	15	2,375	1391 @	1.20
Asphalt: Repairs-Moon Valley Terra..	2014	2019	536	5	0	3	575	4750 @	3.75
Asphalt: Repairs-Path	2011	2016	846	5	0	0	846	4510 @	3.75
Asphalt: Repairs-Silver Creek Place	2014	2019	829	5	0	3	889	5390 @	3.75
Asphalt: Repairs-Tatum Ranch Place	2014	2019	185	5	0	3	199	1391 @	3.75
Asphalt: Sealcoat-Moon Valley Terr..	2013	2018	665	5	0	2	697	4750 @	0.14
Asphalt: Sealcoat-Path	2013	2018	722	5	0	2	756	4510 @	0.16
Asphalt: Sealcoat-Silver Creek Place	2013	2018	755	5	0	2	791	5390 @	0.14
Asphalt: Sealcoat-Tatum Ranch Place	2013	2018	195	5	0	2	204	1391 @	0.14
Bark Dust: Replace	2015	2017	4,301	2	0	1	4,403	25300 @	0.17
Brick: Pilaster-Wall	2001	2016	7,500	15	0	0	7,500	1 @	7,500.00
Bridge: Wooden-Replacement	2001	2026	17,500	25	0	10	22,141	1 @	17,500.00
Concrete: Flatwork-Sidewalks-Com..	2001	2016	5,582	10	5	0	5,582	2326 @	12.00
Concrete: Flatwork-Sidewalks-Moon..	2001	2016	2,525	10	5	0	2,525	1052 @	12.00
Concrete: Flatwork-Sidewalks-Silver..	2001	2016	3,120	10	5	0	3,120	1300 @	12.00
Curb-Gutter: Moon Valley	2001	2016	2,104	12	3	0	2,104	263 @	8.00
Curb-Gutter: Silver Creek Place	2001	2016	2,600	12	3	0	2,600	325 @	8.00
Curb-Gutter: Tatum Ranch	2001	2016	1,808	12	3	0	1,808	226 @	8.00
Fence: Chain Link	2001	2031	253,685	30	0	15	361,012	11225 @	22.60
Fence: Vinyl	2001	2026	186,144	25	0	10	235,505	9600 @	19.39
Fence: Vinyl-Wash	2014	2020	5,280	6	0	4	5,801	9600 @	0.55
Landscaping: Plants & Arborvitae	2001	2016	6,000	10	5	0	6,000	1 @	6,000.00
Lighting: Fixtures-Monuments	2001	2016	1,110	8	7	0	1,110	6 @	185.00
Lighting: Fixtures-Silver Creek Place..	2001	2021	185	20	0	5	208	1 @	185.00
Lighting: Power-Silver Creek Place-..	2001	2031	185	30	0	15	263	1 @	185.00
Mailboxes: Replace	2001	2031	56,232	30	0	15	80,022	36 @	1,562.00
Signs: Common Area	2001	2016	1,000	10	5	0	1,000	2 @	500.00
Signs: Monument	2001	2016	4,800	10	5	0	4,800	2 @	2,400.00
Storm Drains: Tatum Ranch Place	2001	2031	2,500	30	0	15	3,558	1 @	2,500.00
StormDrains: Moon Valley Terrace	2001	2031	2,500	30	0	15	3,558	1 @	2,500.00
StormDrains: Silver Creek Place	2001	2031	2,500	30	0	15	3,558	1 @	2,500.00
Trees: Renovation-Removal-Trimmi..	2001	2016	12,500	10	5	0	12,500	1 @	12,500.00
Walls: Retaining	2001	2016	10,000	10	5	0	10,000	1 @	50,000.00
Walls: Retaining-Inspection	2015	2025	1,064	10	0	9	1,315	1 @	1,064.00



RESERVE STUDIES BY RESERVE FUNDING

Attached herewith is the reserve study (physical and financial analysis) for the Association. **Interest from reserve savings accounts must stay in the reserve account(s) and not be used as an offset against monthly assessments.**

You are encouraged to thoroughly review this document and its individual reports for conformity to the description of responsibility for the Association's Common Areas and Commonly Maintained Property as those terms are defined in your Declaration of Covenants, Conditions and Restrictions. In addition, please pay close attention to the reserve bank balance estimated to be on hand by your staff. **Any discrepancy in the figure or interest rate can have a significant effect on the reserve study and the outcome of the assumptions shown.**

The intention of the reserve study is to forecast, as they wear out in future years, the Association's ability to repair, replace, restore or maintain major components with a life expectancy of over one year and an estimated cost of over one thousand dollars. The reports will provide the Association's Board of Directors (Board) the information necessary to make the reserve projection disclosures required by existing statutes, lender's requirements, or the governing documents.

The cost outlined in the reserve study is subjective in some areas, therefore we may use costs submitted by the Declarant, Management or the Board, and are for budgetary and planning purposes only. Actual bid costs would depend upon the defined scope of work at the time the repair, replacement or restoration is done, and on actual price levels prevailing at the time the future repair, replacement, or restoration must be done.

The estimates on future repair, replacement and restoration in the reserve study will be good faith estimates and projections, based upon the estimated future inflation rate and interest (yield) on the monies set aside which may or may not prove accurate. Consultant submits that the probability that it may project in its reserve study, or that the Board could project in its disclosures, future costs or actual future remaining useful lives of components having useful lives extended beyond one year with precision is the functional equivalent of winning the lottery (while it may happen in rare instances by chance, one may not reasonably expect it to happen). As a result, Consultant cannot, and does not, warrant or guaranty its projections. Assumptions on future costs and life expectancy's should be reviewed and adjusted on an annualized basis, as current and future cost projections and life expectancy's become more uncertain.

This reserve study is limited to an off-site, on-site or plan take-off physical analysis of the property, and as such did not disturb the major components. Therefore, all Common Areas and Commonly Maintained Property as those terms are defined in the Declaration for which there is no access without defacement are specifically omitted. However, if sufficient historical data including costs were available that would allow a reasonable projection of future expenditures for any unobserved components, e.g., plumbing, utilities, electrical wiring, those components could be included in the reserve study and may require an engineer's report.

Since no destructive testing was undertaken, this reserve study, as stated above, does not purport to address any latent and/or patent defects, nor does it address any life expectancies that are abnormally short due either to improper design or installation, or to subsequent improper maintenance. It is assumed that all components are to be reasonably maintained for the remainder of their life expectancy.

The seals below the signature is evidence that the reserve study was performed under the guidelines and policies of the Association of Professional Reserve Analysts and the Community Association Institute.

Sincerely,

D. L. "Dan" Huntley, PRA, RS
Tamarra "Tammy" Axton, PRA

Association of Professional Reserve Analyst-APRA-(PRA)
Community Association Institute-CAI-(RS) Reserve Specialist



EXECUTIVE SUMMARY

At the direction of the Association that recognizes the need for proper reserve planning, we have prepared a Reserve Study (physical and financial analysis) of the Association's Common Areas and Commonly Maintained Property as those terms are defined in the Declaration and submit our findings in this report. The purpose of this Reserve Study is to establish a reasonable yearly reserve contribution necessary to meet future expenditures for major replacements or repairs of the Common Areas and Commonly Maintained Property as those terms may be defined in the Declaration, as amended, and that components have a life expectancy of more than one year and less than thirty years.

All major Common Areas and Commonly Maintained Property as those terms are defined in the Declaration are likely to require capital repair or replacement over the next thirty years. Our analysis considered current and future costs of replacement for the subject Common Areas and Commonly Maintained Property as those terms are defined in the Declaration, the average annual fund balance, interest on invested funds, and anticipated inflation. Based on the investigation and analysis as detailed in the accompanying narrative, the attached *CURRENT ASSESSMENT FUNDING MODEL PROJECTION* report details the average reserve contributions that are recommended to fund the expected capital expenditures of the subject Common Areas and Commonly Maintained Property as those terms are defined in the Declaration over the next thirty years.

We arrived at these recommendations in part by matching the anticipated expenditures noted in the *ANNUAL EXPENDITURE DETAIL* against current fund balances and the annual levels of funding. **Reserve funds would not become depleted within the next thirty years at the levels of funding recommended.**

The *CURRENT ASSESSMENT FUNDING MODEL PROJECTION* enumerates the details regarding recommended annual reserve contributions and projected year-end reserve balances. We recommend, in accordance with state statutes, subsequent yearly off-site updates of this reserve study and an on-site physical analysis every five years to confirm that the recommended reserve contributions are appropriate in view of possible changes in the property, components not completed as detailed in the expenditure report, interest rates, inflation rates, costs, and movement of any excess operating funds to the reserve savings accounts as approved by the membership.

It is necessary that regular maintenance of the Common Areas and Commonly Maintained Property as those terms are defined in the Declaration be done to insure maximum useful life and optimum performance of the reserve components. Components of concern include items associated with water intrusion and safety.

The maintenance plan is a cyclical plan that calls for regular maintenance at regular intervals and will list the maintenance activity and the frequency of maintenance as well as a short narrative.

Checklists developed by Reed Construction Data, Inc. can be accessed, photocopied or downloaded from the RS Means web site at www.rsmeans.com/supplement/67346.asp. We strongly urge the Board to use these forms.

NARRATIVE REPORT

The following reports illustrate our recommendations and observations concerning anticipated expenditures, recommended reserve funding and projected fund balances during the next thirty years.

We have not investigated the title to or any liabilities against the property subject to this report.

At the direction of the Association, which recognizes the need for proper reserve planning, we have made a reserve study (physical and financial analysis) of this community and submit our findings in this report.

The purpose of this study is to establish a reasonable yearly reserve contribution necessary to meet future expenditures for major replacements or repairs of the Common Areas and Commonly Maintained Property of the Association as those terms are defined in the Declaration as of the beginning of its fiscal year.

Reserves for replacement are estimates of that amount of money that must be put aside to repair or replace major items or building components that will wear out before the entire facility or project wears out.

State law, such as that found in Texas, Nevada, California, Oregon and Washington, clearly establishes the fiduciary duty of “boards” and the necessity for adequate assessments including reserve funds. The legislative intent of these acts is to better protect current owners and future buyers of units in community associations. Reserving funds for future repair or replacement of the shorter-lived building components is also one of the most reliable ways of protecting the future market value of an individual’s investment property from the deleterious effects of special assessments.

For the purposes of this study, the detailed cash flow analysis is limited to those components or elements that are likely to require replacement or major rehabilitation during the next thirty-year period. Replacement of an entire planned development or condominium in 50 to 75 years is not a typical event. Preventive maintenance generally extends the useful life of many components. As such, estimating useful lives beyond thirty years from the date of this study is indeterminate and it is recommended that periodic updates of this study be made to consider actual facts and circumstances regarding extended or diminished component lives, inflation, and appreciation of the reserves.

Our investigation included Common Areas and Commonly Maintained Property as those terms are defined in the Declaration as set forth in your Declaration associated with the property of the Association. Excluded from our consideration was all other property, including land, property owned individually by unit or home owners that is not Commonly Maintained Property, personal property, and intangible assets.

Expenditures relating to the operating budget and apart from reserves are excluded from this reserve analysis. It is our understanding that the operating budget and future operating budgets will provide for the on-going normal maintenance of Common Areas and Commonly Maintained Property as those terms are defined in the Declaration unless specifically identified in the component description on the *DETAIL REPORT BY CATEGORY*.

Our report comprises:

This letter, that sets forth the nature and extent of the investigation, identifies the classes of

property considered, and presents the conclusions reached.

An Executive Summary identifies the property, current reserves, recommended reserve funding, and projections concerning reserve funding.

Consideration and Methodology

The purpose of this study is to estimate the amount of yearly reserve contributions necessary to meet future expenditures for major replacements and repairs of the Common Area and Commonly Maintained Property as those terms are defined in the Declaration of the Association without a special assessment. We reviewed the property subject of this investigation and considered the following:

Local costs of material, equipment and labor combined in the cost factor.

The current and future costs of replacement or repair for the Common Areas and Commonly Maintained Property as those terms are defined in the Declaration as detailed in the *DETAIL REPORT BY CATEGORY*.

The cost of removal if required of the worn out components as part of the cost of replacement.

The anticipated effects of inflation on the amount to be reserved annually.

The anticipated effects of appreciation of the reserves over time in accord with your average current return or yield on investments. **We were informed all accrued interest on Association investments would be included within the reserve funds.**

The past and current maintenance practices of your Association and their effects on remaining lives.

We have not considered as part of the reserve contributions the amounts required for yearly maintenance activities.

SUMMARY AND CONCLUSION

This study indicates that based on the anticipated expenditures noted in the ANNUAL EXPENDITURE DETAIL report, the current reserves and annual recommended levels of funding are adequate to avoid future special assessments. Reserves would not become depleted within the next thirty years at current recommended levels of funding.

ASSUMPTIONS, SCOPE, AND LIMITED CONDITIONS

To the best of our knowledge, all data set forth in this report are true and accurate. Although gathered from reliable sources, no guarantee is made nor liability assumed for the accuracy of any data, opinions, or estimates identified as being furnished by others or ourselves that have been used in formulating this analysis.

No soils analysis or geological studies were ordered or made in conjunction with this report, nor was any water, oil, gas, coal or other subsurface mineral and use rights or conditions investigated.

Any latent defects will not be a part of the reserve study. Should we find signs of possible latent defects or problems not within the scope of the reserve study, the Association will be notified so that the Association can retain the proper experts. However, the study will not be designed to uncover any possible latent defects, and the absence of any indications to such effect will not be, and should not be construed to be, an indication that there are no defects not so noted, or that we warrant the absence of any such defects.

Substances such as fungi, mold, asbestos, lead paint, urea-formaldehyde foam insulation, termite control substances other chemicals, toxic wastes, radon gas, electro-magnetic radiation or other potentially hazardous materials (on the surface or sub-surface) could, if present, adversely affect the validity of our reserve study. Unless otherwise stated in our reserve study, the existence of hazardous substances, that may or may not be present on the property, will not be considered nor will there be any inspection for termites. Our opinions are predicated on the assumption that there is no such material on or in the property nor existence of termites. No responsibility is assumed for any such conditions, and you are advised that we are not qualified to detect such substances, quantify the impact, or develop the remedial cost.

The Association needs to review each line item in the reports to be certain corrections are made from information you may possess that we are not aware of. It is assumed in our reserve study that no work, or expenditures from the reserve funds will occur for the balance of the fiscal year. If this is not correct, you need to let us know what extra work was done and how much money will be spent.

This physical analysis was made by individuals generally familiar with real estate and building construction and 33 years experience preparing reserve studies; however, no invasive testing was performed. Our report does not consider electrical wiring, plumbing or utilities that may be the responsibility of the Association. Accordingly, we do not opine on, nor are we responsible for, the structural integrity of the property, including, but not limited to, its conformity to specific governmental code requirements, such as fire, building safety, earthquake, occupancy, land movement and/or slides, or any physical defects that were not readily apparent in our physical analysis. This reserve study is not an engineering study.

The cost outlined in the reserve study is subjective in some areas; therefore, we may use costs submitted by the Association that are for budgetary and planning purposes only. Actual bid costs would depend upon the defined scope of work at the time the repair, replacement or restoration is done, and on actual price levels prevailing at the time the future repair, replacement or restoration must be done. The estimates on future repair, replacement and restoration in the reserve study will be good faith estimates and projections, based upon the estimated future inflation rate and interest (yield) on the monies set aside which may or may not prove accurate. We submit that the probability that the board may project in its reserve study or disclosures, future costs or actual future remaining useful lives of components having useful lives extended beyond one year with precision is the functional equivalent of winning the lottery (while it may happen in rare instances by chance, one may not reasonably expect it to happen). As a result, we cannot, and do not, guaranty its projections. Assumptions on future costs and life expectancies should be reviewed and adjusted on an annualized basis, as current future costs projections and life expectancies become more uncertain.

PROFESSIONAL SERVICE CONDITIONS

The services provided by Reserve Studies by Reserve Funding© were performed in accordance with our professional practice standards. Our compensation is not contingent in any way upon our conclusions. We assume, without independent verification, the accuracy of all data provided to us. We will act as an independent contractor. All files, work papers or documents developed by us during the course of the engagement will remain our property.

Our report is to be used only for the purposes stated herein. Any use or reliance for any other purpose, by you or third parties, is invalid. You may show our report in its entirety to those third parties that need to review the information contained herein. No reference to our name or our report, in whole or in part, in any document you prepare and/or distribute to third parties may be made without our written consent.

Association shall defend, indemnify, and hold harmless Reserve Studies by Reserve Funding© and its employees and subagents, who were or are a party or are threatened to be made a party to any threatened, pending, or completed actions, suits, or proceedings, whether civil, criminal, administrative, or investigative by reason of the fact that Reserve Studies by Reserve Funding©, and its employees and subagents, are or were the authorized representatives of the Association, as to any expense, including attorneys' fees, judgments, fines, and amounts paid in settlement actually and reasonably incurred by Reserve Studies by Reserve Funding© and its employees and subagents, in connection with such action, suit, or proceeding, if Reserve Studies by Reserve Funding© and its employees and subagents acted in good faith and in a manner Reserve Studies by Reserve Funding© and its employees and subagents reasonably believed to be in, or not opposed to, the best interest of the Association, and with respect to any criminal action or proceeding, had no reasonable cause to believe their conduct was unlawful.

We have prepared an initial draft of the study and will make one adjustment to the report upon a written request from the Association within 30 days of the date the initial draft of the study is sent to the Board.

We reserve the right to include your Association's name in our client list, but we will maintain the confidentiality of all conversations, documents provided to us, and the contents of our reports, subject to legal or administrative process or proceedings.

These conditions can only be modified by written documents executed by both parties.

Respectfully submitted,

D. L. "Dan" Huntley, PRA, RS

Tamarra "Tammy" Axton, PRA

Association of Professional Reserve Analyst-APRA-(PRA)

Community Association Institute-CAI-(RS) Reserve Specialist

Important Information About Your Reserve Study

Important Information

This document has been provided pursuant to an agreement containing restrictions on its use. No part of this document may be copied or distributed, in any form or by any means, nor disclosed to third parties without the expressed written permission of Reserve Studies by Reserve Funding©. The client shall have the right to reproduce and distribute copies of this report, or the information contained within, as may be required for compliance with all applicable regulations.

This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by representatives of the association, its contractors, assorted vendors, specialist and independent contractors, the Community Association Institute, Association of Professional Reserve Analyst and various construction pricing and scheduling manuals including, but not limited to: Marshall & Swift Valuation Service, RS Means Facilities Maintenance & Repair Cost Data, RS Means Repair & Remodeling Cost Data, National Construction Estimator, National Repair & Remodel Estimator, Dodge Cost Manual and McGraw-Hill Professional. Additionally, costs are obtained from numerous vendor catalogues, actual quotations or historical costs, and our own experience in the field of property management and reserve study preparation.

It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and that each estimated useful life will approximate that of the norm per industry standards and/or manufacturer's specifications. In some cases, estimates may have been used on assets, which have an indeterminable but potential liability to the association. The decision for the inclusion of these as well as all assets considered is left to the client.

We recommend that your reserve analysis study be updated on an annual basis due to fluctuating interest rates, inflationary changes, and the unpredictable nature of the lives of many of the assets under consideration (our contract provides that we shall update the reserve study annually). All of the information collected during our physical analysis of the association and computations made subsequently in preparing this reserve analysis study are retained in our computer files. Therefore, annual updates may be completed quickly and inexpensively each year.

Reserve Studies by Reserve Funding© would like to thank you for using our services. We invite you to call us at any time, should you have questions, comments or need assistance. In addition, any of the parameters and estimates used in this study may be changed at your request, after which we will provide a revised study. Client shall accept all responsibility and liability for changes made and the results thereof. Consultant does not warranty the results of the revised study.

This reserve analysis study is provided as an aid for planning purposes and not as an accounting tool. Since it deals with events yet to take place, there is no assurance that the results enumerated within it will, in fact, occur as described.

Part III

Introduction

Preparing the annual budget and overseeing the association's finances are perhaps the most important responsibilities of board members. The annual operating and reserve budgets reflect the planning and goals of the association and set the level and quality of service for all of the association's activities.

Funding Options

When a major repair or replacement is required in a community, an association has essentially four options available to address the expenditure:

The first, and only logical means that the Board of Directors has to ensure its ability to maintain the assets for which it is obligated, is by **assessing an adequate level of reserves** as part of the regular membership assessment, thereby distributing the cost of the replacements uniformly over the entire membership. The community is not only comprised of present members, but also future members. Any decision by the Board of Directors to adopt a calculation method or funding plan which would disproportionately burden future members in order to make up for past reserve deficits, would be a breach of its fiduciary responsibility to those future members. Unlike individuals determining their own course of action, the board is responsible to the "community" as a whole.

Whereas, if the association was setting aside reserves for this purpose, using the vehicle of the regularly assessed membership dues, it would have had the full term of the life of the roof, for example, to accumulate the necessary monies. Additionally, those contributions would have been evenly distributed over the entire membership and would have earned interest as part of that contribution.

The second option is for the association to **acquire a loan** from a lending institution in order to effect the required repairs. In many cases, banks will lend to an association using "future homeowner assessments" as collateral for the loan. With this method, the current board is pledging the future assets of an association. They are also incurring the additional expense of interest fees along with the original principal amount. In the case of a \$150,000 roofing replacement, the association may be required to pay back the loan over a three to five year period, with interest.

The third option, too often used, is simply to defer the required repair or replacement. This option, which is not recommended, can create an environment of declining property values due to expanding lists of deferred maintenance items and the association's financial inability to keep pace with the normal aging process of the common area components. This, in turn, can have a seriously negative impact on sellers in the association by making it difficult, or even impossible, for potential buyers to obtain financing from lenders. Increasingly, lending institutions are requesting copies of the association's most recent reserve study before granting loans, either for the association itself, a prospective purchaser, or for an individual within such an association.

The fourth option is to pass a “**special assessment**” to the membership in an amount required to cover the expenditure. When a special assessment is passed, the association has the authority and responsibility to collect the assessments, even by means of foreclosure, if necessary. However, an association considering a special assessment cannot guarantee that an assessment, when needed, will be passed. Consequently, the association cannot guarantee its ability to perform the required repairs or replacements to those major components for which it is obligated when the need arises. Additionally, while relatively new communities require very little in the way of major “reserve” expenditures, associations reaching 12 to 15 years of age and older, find many components reaching the end of their effective useful lives. These required expenditures, all accruing at the same time, could be devastating to an association’s overall budget.

Types of Reserve Studies

Most reserve studies fit into one of three categories:

Full Reserve Study;

Update with site inspection; and

Update without site inspection.

In a **Full Reserve Study**, the reserve provider conducts a component inventory, a condition assessment (based upon on-site visual observations), and life and valuation estimates to determine both a “fund status” and “funding plan”.

In an **Update with site inspection**, the reserve provider conducts a component inventory (verification only, not quantification unless new components have been added to the inventory), a condition assessment (based upon on-site visual observations), and life and valuation estimates to determine both the “fund status and “funding plan.”

In an **Update without site inspection**, the reserve provider conducts life and valuation estimates to determine the “fund status” and “funding plan.”

The Reserve Study: A Physical and a Financial Analysis

There are two components of a reserve study: a physical analysis and a financial analysis.

Physical Analysis

During the physical analysis, a reserve study provider evaluates information regarding the physical status and repair/replacement cost of the association’s major common area components. To do so, the provider conducts a component inventory, a condition assessment, and life and valuation estimates.

Developing a Component List

The budget process begins with full inventory of all the major components for which the association is responsible. The determination of whether an expense should be labeled as operational, reserve, or excluded altogether is sometimes subjective. Since this labeling may have a major impact on the financial plans of the association, subjective determinations should be minimized. We suggest the following considerations when labeling an expense.

Operational Expenses

Occur at least annually, no matter how large the expense, and can be effectively budgeted each year. They are characterized as being reasonably predictable, both in terms of frequency and cost. Operational expenses include all minor expenses, which would not otherwise adversely affect an operational budget from one year to the next. Examples of *some operational expenses* include:

Utilities:	Administrative:	Services:	Repair Expenses:
Electrical/Lights	Supplies	Landscape	Operating Contingency
Water/Irrigation	Bank Service Charges	Reserve Study Costs	
	Insurance		

These are major expenses that occur other than annually, and which must be budgeted in advance in order to ensure the availability of the necessary funds in time for their use. Reserve expenses are reasonably predictable both in terms of frequency and cost. However, they may include significant assets that have an indeterminable but potential liability that may be demonstrated as a likely occurrence. They are expenses that, when incurred, would have a significant effect on the smooth operation of the budgetary process from one year to the next, if they were not reserved in advance. Examples of some reserve expenses include:

Asphalt Seal Coating	Painting-Mail Box Structures
Asphalt Overlays	Lighting Replacement
Asphalt Repair or Replacement	Underground Utilities
Masonry Repair	Concrete Curbs, Sidewalks, Aprons, and Parking Pads
Fencing Repair and Replacement	Insurance Deductible

Budgeting is Normally Excluded for:

Repairs or replacements of assets which are deemed to have an estimated useful life equal to or exceeding the estimated useful life of the facility or community itself, or exceeding the legal life of the community as defined in an association's governing documents. Examples include the complete replacement of masonry walls and concrete. Also excluded are insignificant expenses that may be covered either by an operating or reserve contingency, or otherwise in a general maintenance fund. Expenses that are necessitated by acts of nature, accidents, or other occurrences that are more properly insured, rather than reserved, are also excluded.

Financial Analysis

The financial analysis assesses the association's reserve balance or "fund status" (measured in cash or as percent fully funded) to determine a recommendation for the appropriate reserve contribution rate in the future, known as the "funding plan."

Preparing the Reserve Study

Once the reserve assets have been identified and quantified, their respective replacement costs, useful lives, and remaining lives must be assigned so that a funding schedule can be constructed. Replacement costs and useful lives can be found in published manuals such as construction estimators, appraisal handbooks, and valuation guides. Remaining lives are calculated from the useful lives and ages of assets and adjusted according to conditions such as design, manufactured quality, usage, exposure to the elements, and maintenance history.

By following the recommendations of an effective reserve study, the association should avoid any major shortfalls. However, to remain accurate, the report should be updated on an annual basis to reflect such changes as shifts in economic parameters, additions of phases or assets, or expenditures of reserve funds. The association can assist in simplifying the reserve analysis update process by keeping accurate records of these changes throughout the year.

Funding Methods

From the simplest to the most complex, reserve analysis providers use many different computational processes to calculate reserve requirements. However, there are two basic processes identified as industry standards: the cash flow method and the component method.

The cash flow method develops a reserve-funding plan where contributions to the reserve fund are designed to offset the variable annual expenditures from the reserve fund. Different reserve funding plans are tested against the actual anticipated schedule of reserve expenses until the desired funding goal is achieved. This method sets up a “window” in which all future anticipated replacement costs are computed, based upon the individual lives of the components under consideration. The Reserve Studies by Reserve Funding© Threshold and the Reserve Studies by Reserve Funding© Current Assessment funding models are based upon the cash flow method.

The component method develops a reserve-funding plan where the total contribution is based upon the sum of contributions for individual components. The component method is the more conservative of the two funding options, and assures that the association will achieve and maintain an ideal level of reserve over time. This method also allows for computations on individual components in the analysis. The Reserve Studies by Reserve Funding© Component Funding model is based upon the component methodology.

Funding Strategies

Once an association has established its funding goals, the association can select an appropriate funding plan. There are four basic strategies from which most associations select. It is recommended that associations consult professionals to determine the best strategy or combination of plans that best suit the association's need. Additionally, associations should consult with their financial advisor to determine the tax implications of selecting a particular plan. Further, consultation with the American Institute of Certified Public Accountants (AICPA) for their reporting requirements is advisable. The four funding plans and descriptions of each are detailed below. Associations will have to update their reserve studies more or less frequently depending on the funding strategy they select.

Full Funding---Given that the basis of funding for reserves is to distribute the costs of the replacements over the lives of the components in question, it follows that the ideal level of reserves would be proportionately related to those lives and costs. If an association has a component with an expected estimated useful life of ten years, it would set aside approximately one-tenth of the replacement cost each year. At the end of three years, one would expect three-tenths of the replacement cost to have accumulated, and if so, that component would be "fully-funded." This model is important in that it is a measure of the adequacy of an association's reserves at any one point of time, and is independent of any particular method which may have been used for past funding or may be under consideration for future funding. This formula represents a snapshot in time and is based upon current replacement cost, independent of future inflationary or investment factors:

Fully Funded Reserves = Age divided by Useful Life the results multiplied by Current Replacement Cost

When an association's total accumulated reserves for all components meet this criterion, its reserves are considered "fully-funded."

The Reserve Studies by Reserve Funding © **Threshold Funding Model (Minimum Funding)**. The goal of this funding method is to keep the reserve cash balance above zero. This means that while each individual component may not be fully funded, the reserve balance overall does not drop below zero during the projected period. An association using this funding method must understand that even a minor reduction in a component's remaining useful life can result in a deficit in the reserve cash balance.

The Reserve Studies by Reserve Funding © **Threshold Funding Model**. This method is based upon the cash flow funding concept. The minimum reserve cash balance in threshold funding, however, is set at a predetermined dollar amount (other than \$0).

The Reserve Studies by Reserve Funding © **Current Assessment Funding Model**. This method is also based upon the cash flow funding concept. The initial reserve assessment is set at the association's current fiscal year funding level and a 30-year projection is calculated to illustrate the adequacy of the current funding over time.

The Reserve Studies by Reserve Funding © **Component Funding Model**. This is a straight-line funding model. It distributes the cash reserves to individual reserve components and then calculates what the reserve assessment and interest contribution (minus taxes) should be, again by each reserve component. The current annual assessment is then determined by summing all the individual component assessments, hence the name “Component Funding Model”. This is the most conservative funding model. It leads to or maintains the fully funded reserve position. The following details this calculation process.

Distribution of Reserves

Component Funding Model Distribution of Accumulated Reserves

The “Distribution of Accumulated Reserves Report” is a “Component Funding Model” calculation. This distribution **does not** apply to the cash flow funding models.

When calculating reserves based upon the component methodology, a beginning reserve balance must be allocated for each of the individual components considered in the analysis, before the individual calculations can be completed. When this distribution is not available, or of sufficient detail, the following method is suggested for allocating reserves:

The first step the program performs in this process is subtracting, from the total accumulated reserves, any amounts for assets that have predetermined (fixed) reserve balances. The user can “fix” the accumulated reserve balance within the program on the individual asset’s detail page. If, by error, these amounts total more than the amount of funds available, then the remaining assets are adjusted accordingly. A provision for a contingency reserve is then deducted by the determined percentage used, and if there are sufficient remaining funds available.

The second step is to identify the ideal level of reserves for each asset. As indicated in the prior section, this is accomplished by evaluating the component’s age proportionate to its estimated useful life and current replacement cost. Again, the equation used is as follows:

Fully Funded Reserves = (Age/Useful Life) x Current Replacement Cost

The Reserve Studies by Reserve Funding® software program performs the above calculations to the actual month the component was placed-in-service. The program projects that the accumulation of necessary reserves for repairs or replacements will be available on the first day of the fiscal year in which they are scheduled to occur.

The next step the program performs is to arrange all of the assets used in the study in ascending order by remaining life, and alphabetically within each grouping of remaining life items. These assets are then assigned their respective ideal level of reserves until the amount of funds available is depleted, or until all assets are appropriately funded. If any assets are assigned a zero remaining life (scheduled for replacement in the current fiscal year), then the amount assigned equals the current replacement cost and funding begins for the next cycle of replacement. If there are insufficient funds available to accomplish this, then the software automatically adjusts the zero remaining life items to one year, and that asset assumes its new grouping position alphabetically in the final printed report.

If, at the completion of this task, there are additional moneys that have not been distributed, the remaining reserves are then assigned, in ascending order, to a level equal to, but not exceeding, the current replacement cost for each component. If there are sufficient moneys available to fund all assets at their current replacement cost levels, then any excess funds are designated as such and are not factored into any of the report computations. If, at the end of this assignment process there are designated excess funds, they can be used to offset the monthly contribution requirements recommended, or used in any other manner the client may desire.

Assigning the reserves in this manner defers the make-up period for any under-funding over the longest remaining life of all assets under consideration, thereby minimizing the impact of any deficiency. For example, if the report indicates an under funding of \$50,000, this under-funding will be assigned to components with the longest remaining lives in order to give more time to “replenish” the account. If the \$50,000 under-funding were to be assigned to short remaining life items, the impact would be felt immediately.

If the reserves are under-funded, the monthly contribution requirements, as outlined in this report, can be expected to be higher than normal. In future years, as individual assets are replaced, the funding requirements will return to their normal levels. In the case of a large deficiency, a special assessment may be considered. The program can easily generate revised reports outlining how the monthly contributions would be affected by such an adjustment, or by any other changes that may be under consideration.

Funding Reserves

Three assessment and contribution figures are provided in the report, the “Monthly Reserve Assessment Required”, the “Average Net Monthly Interest Earned” contribution and the “Total Monthly Allocation to Reserves.” The association should allocate the “Monthly Reserve Assessment Required” amount to reserves each month when the interest earned on the reserves is left in the reserve accounts as part of the contribution. Any interest earned on reserve deposits, must be left in the reserve account and only amounts set aside for taxes should be removed .

The second alternative is to allocate the "Total Monthly Allocation" to reserves (this is the member assessment plus the anticipated interest earned for the fiscal year. This method assumes that all interest earned will be assigned directly as operating income. This allocation takes into consideration the anticipated interest earned on accumulated reserves regardless of whether or not it is actually earned. When taxes are paid, the amount due will be taken directly from the association's operating accounts as the reserve accounts are allocating only those moneys net of taxes.

Users' Guide to your Reserve Analysis Study

Part II of your Reserve Funding© Report contains the reserve analysis study for your association. There are seven types of reports in the study as described below.

Report Summaries

The Report Summary for all funding models lists all of the parameters that were used in calculating the report as well as the summary of your reserve analysis study.

Index Reports

The **Distribution of Accumulated Reserves** report lists all assets in remaining life order. It also identifies the ideal level of reserves that should have accumulated for the association as well as the actual reserves available. This information is valid only for the "Component Funding Model" calculation.

The **Component Listing/Summary** lists all assets by category (i.e. roofing, painting, lighting, etc.) together with their remaining life, current cost, monthly reserve contribution, and net monthly allocation.

Detail Reports

The Detail Report itemizes each asset and lists all measurements, current and future costs, and calculations for that asset. Provisions for percentage replacements, salvage values, and one-time replacements can also be utilized. These reports can be sorted by category or group.

The numerical listings for each asset are enhanced by extensive narrative detailing factors such as design, manufactured quality, usage, exposure to elements and maintenance history.

The Reserve Studies by Reserve Funding© Detail Index is an alphabetical listing of all assets, together with the page number of the asset's detail report, the projected replacement year, and the asset number.

Projections

Thirty-year projections add to the usefulness of your reserve analysis study.

Definitions

Report I.D.

Includes the Report Date (example: June 19, 2006), Account Number (example: 9773), and Version (example: 1.0). Please use this information (displayed on the summary page) when referencing your report.

Budget Year Beginning/Ending

The budgetary year for which the report is prepared. For associations with fiscal years ending December 31st, the monthly contribution figures indicated are for the 12-month period beginning 1/1/20xx and ending 12/31/20xx.

Number of Units and/or Phases

If applicable, the number of units and/or phases included in this version of the report.

Inflation

This figure (information taken from "Inflationdata.com" and averaged over 5 years is used to approximate the future cost to repair or replace each component in the report. The current cost for each component is compounded on an annual basis by the number of remaining years to replacement, and the total is used in calculating the monthly reserve contribution that will be necessary to accumulate the required funds in time for replacement.

Annual Assessment Increase

This represents the percentage rate at which the association will increase its assessment to reserves at the end of each year. For example, in order to accumulate \$10,000 in 10 years, you could set aside \$1,000 per year. As an alternative, you could set aside \$795 the first year and increase that amount by 5% each year until the year of replacement. In either case you arrive at the same amount. The idea is that you start setting aside a lower amount and increase that number each year in accordance with the planned percentage. Ideally this figure should be equal to the rate of inflation. It can, however, be used to aide those associations that have not set aside appropriate reserves in the past, by making the initial year's allocation less formidable.

Investment Yield Before Taxes

The average interest rate anticipated by the association based upon its current investment practices.

Taxes on Interest Yield

The estimated percentage of interest income that will be set aside to pay income taxes on the interest earned.

Projected Reserve Balance

The anticipated reserve balance on the first day of the fiscal year for which this report has been prepared. This is based upon information provided and not audited.

Percent Fully Funded

The ratio, at the beginning of the fiscal year, of the actual (or projected) reserve balance to the calculated fully funded balance, expressed as a percentage.

Phase Increment Detail and/or Age

Comments regarding aging of the components on the basis of construction date or date of acceptance by the association.

Monthly Assessment

The assessment to reserves required by the association each month.

Interest Contribution (After Taxes)

The interest that should be earned on the reserves, net of taxes, based upon their beginning reserve balance and monthly contributions for one year. This figure is averaged for budgeting purposes.

Total Monthly Allocation

The sum of the monthly assessment and interest contribution figures.

Group and Category

The report may be prepared and sorted either by group (location, building, phase, etc.) or by category (roofing, painting, etc.). The standard report printing format is by category.

Percentage of Replacement or Repairs

In some cases, an asset may not be replaced in its entirety or the cost may be shared with a second party. Examples are budgeting for a percentage of replacement of streets over a period of time, or sharing the expense to replace a common wall with a neighboring party.

Placed-In-Service Date

The month and year that the asset was placed-in-service. This may be the construction date, the first escrow closure date in a given phase, or the date of the last servicing or replacement.

Estimated Useful Life

The estimated useful life of an asset based upon industry standards, manufacturer specifications, visual inspection, location, usage, association standards and prior history. All of these factors are taken into consideration when tailoring the estimated useful life to the particular asset. For example, the carpeting in a hallway or elevator (a heavy traffic area) will not have the same life as the identical carpeting in a seldom-used meeting room or office.

Adjustment to Useful Life

Once the useful life is determined, it may be adjusted, up or down, by this separate figure for the current cycle of replacement. This will allow for a current period adjustment without affecting the estimated replacement cycles for future replacements.

Estimated Remaining Life

This calculation is completed internally based upon the report's fiscal year date and the date the asset was placed-in-service.

Replacement Year

The year that the asset is scheduled to be replaced. The appropriate funds will be available by the first day of the fiscal year for which replacement is anticipated.

Annual Fixed Reserves

An optional figure which, if used, will override the normal process of allocating reserves to each asset.

Fixed Assessment

An optional figure which, if used, will override all calculations and set the assessment at this amount. This assessment can be set for monthly, quarterly or annually as necessary.

Salvage Value

The salvage value of the asset at the time of replacement, if applicable.

One-Time Replacement

Notation if the asset is to be replaced on a one-time basis.

Current Replacement Cost

The estimated replacement cost effective at the beginning of the fiscal year for which the report is being prepared.

Future Replacement Cost

The estimated cost to repair or replace the asset at the end of its estimated useful life based upon the current replacement cost and inflation.

Component Inventory

The task of selecting and qualifying reserve components. This task can be accomplished through on-site visual, review of association design and organizational documents, a review of established association precedents, and discussion with appropriate association representative(s).

A Multi-Purpose Tool

Your Reserve Studies by Reserve Funding © Report is an important part of your association's budgetary process. Following its recommendations should ensure the association's smooth budgetary transitions from one fiscal year to the next, and either decrease or eliminate the need for "special assessments".

In addition, your Reserve Studies by Reserve Funding© reserve study serves a variety of useful purposes:

- Following the recommendations of a reserve study performed by a professional consultant can protect the Board of Directors in a community from personal liability concerning reserve components and reserve funding.
- A reserve analysis study is required by your accountant during the preparation of the association's annual audit.
- The Reserve Studies by Reserve Funding© reserve study is often requested by lending institutions during the process of loan applications, both for the community and, in many cases, the individual owners.
- Your Reserve Studies by Reserve Funding© Report is also a detailed inventory of the association's major assets and serves as a management tool for scheduling, coordinating and planning future repairs and replacements.
- Your Reserve Studies by Reserve Funding© Report is a tool that can assist the Board in fulfilling its legal and fiduciary obligations for maintaining the community in a state of good repair. If a community is operating on a special assessment basis, it cannot guarantee that an assessment, when needed, will be passed. Therefore, it cannot guarantee its ability to perform the required repairs or replacements to those major components for which the association is obligated.
- Since the Reserve Studies by Reserve Funding© reserve analysis study includes measurements and cost estimates of the client's assets, the detail reports may be used to evaluate the accuracy and price of contractor bids when assets are due to be repaired or replaced.
- The Reserve Studies by Reserve Funding© reserve study is an annual disclosure to the membership concerning the financial condition of the association, and may be used as a "consumers' guide" by prospective purchasers.
- The Reserve Studies by Reserve Funding© Owners' Summary meets the disclosure requirements of the Texas Timeshare Act
- Your Reserve Studies by Reserve Funding© Report provides a record of the time, cost, and quantities of past reserve replacements. At times the association's management company and board of directors are transitory which may result in the loss of these important records.